
Bi weekly Field Report

Surveyor Date visited Time visited Zaw La 4 Jan 2019 15:00 pm

Weather Condition Sunny
The last time of heavy raining

No	Item	Condition	Narrative Description and Photos	
1	(1.1) Water Supply System	Improved □ Same •* Worse □ *as last week	Narrative Description Water distribution system has been sup zone B resettled families. The new well pipe line and its necessary instruments of the previous well includes iron hydrologged in the iron removal tank. The good and no iron hydroxide and yellow Photos	Il was drilled and installed the because the underground water oxide and yellowish mud that current water condition is quite
			Western from proposed western tour!	
			Water from ground water tank	Pipe line distribution water to houses

No	Item	Condition	Narrative Description and Photos	
1	(1.2) Well	Improved□ Same ■* Worse □ *as last week	living. There are eleven tube well the water basically from the pip frequency of water usage from the	lean enough to use for drinking and ls in the relocation site. Residents use beline distribution system so that the he tube wells is very low. To sustain wells, the leg pumps were kept and aps till the residents use.
			Open Well No. 1	Open Well No. 2
	(2) Drainage	Improved□ Same •* Worse □ *as last week	The drain at the corner of Main Road A and B The exit of the drain at the corner of Site village road and 3 rd street	The exit of the drain at the corner of Site village road and 2 nd street The exit of the drain at the corner of Site village road and Amain Road C
	(3) Road	Improved□ Same •*	All the roads are getting dry are	nd no problem for walking.
		Worse □	Photos	



		7 th Street	Site Village
(4) Garbage Condition	Improved□ Same ■* Worse □ *as last week	of each road until the end of Apri are kept by the community leader near the triangle junction of Main	e bins are provided. been provided and placed at the corner l. After April 2018, all the garbage bins of PAPs in the communal compound Road C and Upper Fourth Street. But e truck from township municipal office
		Rubbishes in the creek near 1st street	Rubbishes in the creek near 2nd street
		Rubbishes in the creek near Main Road C	Rubbishes in the creek near 6 th Street

(5) Fly	
proof	
toilet	

Improved□
Same ■*
Worse □
*as last week

- All of the fly proof toilets are used the residents.
- All of the toilets are repaired by the following procedures;
 - Installation the extra septic tanks beside the original
 - The pipe line system is installed from the extra tank to the ditch to flow the liquid out.

The toilet renovation plan was successfully done and there is no problem at the moment.

	No. of H	ΙΗs
Condition	This week condition	Previous
		week condition
Level 1	91	91
Level 2	0	0
Level 3	0	0
Level 4	0	0
No Toilet	0	0

<Evaluation Criteria>

Level 1

- Fly proof toilet is not needed to be repaired.
- No/rarely toilet unavailable

Level 2

- Fly proof toilet is needed to be repaired.
- Rarely toilet unavailable

Level 3

- Fly proof toilet is needed to be repaired.
- Often toilet unavailable
- As the result of filling the soil and also due to the heavy rain, some toilets are inconvenience to use.

Level 4

- Fly proof toilet is urgently needed to be repaired.
- Often toilet unavailable

Photos









	(6) Electricity	Improved□ Same ■* Worse □ *as last week	 Residents get the electricity regularly. Electric poles and transformer are being supported with the good foundations. There are some pieces of wood under an electric pole of main road B and it's needed to clean up. Photos Transformer No. 1 Transformer No. 2 Electric poles of Main Road B and Main Road C
No	Item	Condition	Description and Photos
2	(1)House Construct- ion	No. of houses which are not completed (4)	 In plot No.9 and 10, three houses that are planned to build as the plots are owned by father and son. Construction has been finished for two houses and one house is not finished yet. Plot No.64, the house construction seems to be stopped. Plot No.78, the house construction is needed to be carried on, however PAPs are living now. Plot No. 66, the house construction for the first floor has been finished and the second floor is still needed to be carried on.
			House No. 9 House No. 64





3 Other Issues

(1). Drainage condition for rain water in the compounds

Description

	No. of HHs	
Condition	This week	Previous week
	condition	condition
Level 1	85	85
Level 2	6	5
Level 3	0	0
Level 4	0	1

<Evaluation Criteria>

Level 1

-No mud and no standing water with their own drainage system in their compound

Level 2

-No mud and no standing water in their compound


Level 3

- Some or little mud and standing water in their compound

Level 4

-A lot of mud and standing water in their compound

Photos





(2) Plantation

In front of the compounds, the shady trees, fruit trees, flowering plants and vegetables are being planted.

Description

- In front of the compounds, the shade trees, fruit trees, flowering plants and vegetables are being planted.

T.		
Type	No. of	Remarks
	HHs	
Shade tree	15	Albizzia, Indian almond, Neem tree, etc.
		HH No. 20, 40, 43, 48, 51, 57, 59, 61, 62, 67,
		69, 72, 73, 77, 85
		05, 72, 73, 77, 03
Fruit tree	37	Banana, Mango, sugar cane, coconut, citrus
		and jack fruit etc.
		HH No. 3, 15, 17, 20,21, 23, 28, 30, 31, 32, 34,
		37, 40, 41, 48, 51, 52, 55, 57, 58, 59, 61, 62,
		63, 67, 68, 70, 71, 72, 73, 77, 78, 82, 85, 86, 88
Vegetables	20	Chili, tomato, bitter gourd, Roselle, gourd,
		basils, eggplant etc.
		HH No. 12, 17, 21, 41, 49, 58, 59, 61, 62, 63,
		67, 68, 70, 71, 72, 73, 77, 82, 85, 86
Flowering	31	Jasmine, poinsettia, orchid, kiss me quick, etc.
plant		HH No. 3, 5, 6, 8, 10, 12, 13, 14, 17, 20, 21,
		22, 23, 29, 30, 31, 32, 46, 48, 58, 59, 61, 62,
		65, 67, 68, 69, 72, 77, 78, 86

Photos,









(3) Livestock

Description

Type	No. of HHs	Remarks
Chicken	6	HH No. 13, 14, 21,
		59, 67, 78
Duck	3	HH No.12
Goose	2	HH No. 40, 67

Photos



