## Surveyor:ZawLaDate Visited:15.2.2016Time Visited:10:30 to 11:30

Weather Condition: Sunny The last time of heavy raining: -

No	Item	Condition	Description and Photos			
1	Condition of	of -				
	(1). Well	Improved□ Same <b>©</b> * Worse □ *as last week	Description & Photos: -See ANNEX.1 - Water from both of two wells are clean and enough to use for drinking and living. One of the hand pumps needs to be repaired, but people can get water from their own tube-wells, some hand pumps and the two wells.			
	(2). Drainage	Improved□ Same <b>©</b> * Worse □ *as last week	<u>Description</u> -Water level in the drainage canals are the same as last week because there was no rain. The stream along the drainage canal may need to be rehabilitated in coming summer period in order to improve the water-flow along the stream. <u>Photos</u>			
			Near Well No. 1         Near HH No. 48         Image: Near			
			Near HH No. 1       Near garbage pit         Image: Ima			

		In front of HH No. 1		
(3). Road	Improved ■* Same □ Worse □ *as last	Description -The roads are being dry and no problem for walking. <u>Photos</u>		
	week	Front main road	The right road of relocation site	
		Middle road	The left road of relocation site	
(4). Garbage Condition	Improved□ Same <b>©</b> * Worse □	<u>Description</u> - People do not want to use garbage pit agai - They do not like people to wash shower ne demolished and water storage tank has bee -Trash from all houses will be collected by ga community fund. -There is a small vegetable planting field at t were many trashes in ten days ago.	ear the well and therefore garbage pit was n constructed instead of it. arbage truck biweekly until starting of the	

		ſ	1			
			Garber pit       Washing clothes and taking bath place         Image: Stress of the stres of the stress of the stress of the stress			
			Back side of third role			
<u>N</u> <u>0</u> 1	<b>Item</b> (5). Fly proof toilet	Condition Improved ■* Same □ Worse □ *as last week	Description         -All of the fly proof toilets are used by people.         -Almost all of the fly proof toilets made by wood or bamboo have been lifted up as shown in pictures below and are convenient to use. Some concrete toilets are still needed to be renovated. According to discussion with community people, they would like to repair the concrete toilets by themselves and requested for financial support.         JET had already paid for it.         Image: The condition of the previous week week condition condition         Level 1       50         So       50         Level 2       17         Level 3       0         No Toilet       1         Fly proof toilet is not needed to be repaired.         -No/rarely toilet unavailable         Level 2         Previous week         Veek         Veek         Very 1			
			<ul> <li>-Rarely toilet unavailable</li> <li>Level 3</li> <li> Fly proof toilet is needed to be repaired.</li> <li>-Often toilet unavailable</li> <li>-As the result of filling the soil and also raining, some toilets are inconvenience to use.</li> <li>Level 4</li> <li>- Fly proof toilet is urgently needed to be repaired.</li> <li>-Often toilet unavailable</li> </ul>			



No	Item	Condition					
2	House Construct -ion	No. of houses not completed (2)	of <u>Description</u> ses not -HH No.5, the construction for kitchen, toilet and water tank seems to be stopped				
-		Description					
3							
I	Status of	(1) House ow	•	owned by DADs (47)			
	PAPs (Sald			owned by PAPs (47)			
	(Sold		No. of house that we	re sold (21)			
	house,	(2) Living con	No. of houses where	DABc(inc(28))			
	renting, etc.)						
	etc.)		(2)-2 No. of houses where original PAPs do not live (22)				
		(2)-3 No. of houses where nobody lives (6) Location Map: See ANNEX.2					
4	Other issue		. 500 / 111/2/12				
	(1). Drainag		n				
	condition fo						
	rain water i	n	No. of HHs				
	their	Conditio		Previous week			
	compounds	5	condition	condition			
l.		Level 1	63	63			
		Level 2	5	5			
		Level 3	0	0			
		Level 4	0	0			
		Level 1 -No mud 3 Level 2 -No mud 3 Level 3 - Some of Level 4	and no standing wate	er with their own drainage system in their com er in their compound ling water in their compound ter in their compound	pound		

		<u>Photos</u>			
		HH No. 47		Level 1 HH No. 45 Level 1	vel 3
		HH No. 61		Level 4         Image: https://www.image.org/amag	vel 2
4	(2) Plantation	Description	ir compounds	, the people planted shady trees, fruit trees, vegetabl	es and floral
		plants.	in compounds,		
		Туре	No. of HHs	Remarks	
		Shady tree	21	Albizzia, Indian almond, etc. HH No. 2, 3, 14, 15,16, 17, 18, 19, 20, 23, 25, 26, 27, 32, 33, 39, 41, 44, 48, 58 and 65	
		Fruit tree	27	Banana, Mango, sugarcane, coconut, citrus, etc. HH No.1, 2, 3, 4, 8, 9, 11, 17, 24, 25, 27, 29, 30, 34, 36, 37, 38, 39, 40, 41, 43, 45, 46, 47, 48, 65 and 67	
		Vegetable	11	Spices, peas, roselle, etc. HH No. 15, 23, 25, 38, 39, 40, 42,45, 58, 63 and 67	
		Floral plant	26	Many species. HH No. 2, 9, 14, 15, 17, 18, 19, 21, 26, 27, 30, 31, 32, 33, 38, 39, 40, 41, 42, 43, 47, 48, 58, 59, 62 and 65	



## ANNEX.1

## As of 15.2.2016

