Surveyor: Zaw La Date Visited: 20.11.2015 Time Visited: 15:30 to 16:00

Weather Condition: Sunny The last time of heavy raining: -

No	Item	Condition	Description and Photos			
1	Condition of	of -				
	(1). Well	Improved□ Same © *	Description & Photos: -See ANNEX.1 - Although both of the two open wells are dirty, it seems that muddy water under the			
		Worse □ *as last	ground is passing through the crack at the wall of the well. The same as last week, both wells cannot be used and therefore people use hand pumps at the moment. In			
		week	terms of avoiding the muddy groundwater passing into the well, both open wells need to be renovated again in summer. One of the hand pump need to be repaired, but people get water from their own tube-well.			
	(2).	Improved□	Description			
	Drainage	Same 🛛*	-Water level in the drainage canals are decreased than last week because there was			
		Worse 🗆	no rain. The stream along the drainage canal may need to be rehabilitated in coming			
		*as last week	summer period in order to improve the water-flow along the stream.			
			Photos			
			Near Well No. 1 Near HH No. 48 Image: Near			
			Near HH No. 1 Near garbage pit Image:			

		In front of HH No. 1
(3). Road	Improved •* Same · Worse · *as last	Description -The roads are being dry and no problem for walking. <u>Photos</u>
	week	Front main road The right road of relocation site Image: state s
		Middle road The left road of relocation site Image: Stress of the left road of the left road of relocation site Image: Stress of the left road of the
(4). Garbage Condition	Improved□ Same © * Worse □	<u>Description</u> -Garbage pit is being used by people. -Garbage pit was gradually increased with trash about half-full again and it needs to be collected again. -People throw garbage at the backside of Third Row and it needs to be clean up too.

			<image/>				
N	<u>ltem</u>	Condition	Description				
<u>o</u> 1	(5). Fly proof	-All of fly proof toilets are used by people. -Almost all of fly proof toilets made by wood or bamboo have been lifted up as shown					
	toilet	Same 🗆	in pictures below and are convenient to use. Some concrete toilets are still need to be				
		Worse 🗆	renovated. According to discussion with community people, the concrete toilets are would like to be repaired by themselves and they requested for financial support. JET				
		*as last	had already paid for it.				
		week	No. of HHs				
			Condition This Previous				
			week week condition condition				
			Level 1 50 50				
			Level 2 17 17				
			Level 3 0 0				
			Level 4 0 0				
			No Toilet 1 1				
			<evaluation criteria=""> Level 1</evaluation>				
			- Fly proof toilet is not needed to be repaired.				
		-No/rarely toilet unavailable					
Level 2 - Fly proof toilet is needed to be repaired.							
		-Rarely toilet unavailable Level 3					
			Fly proof toilet is needed to be repaired.				
		-Often toilet unavailable					
	-As the result of filling the soil and also raining, some toilets are inconvenience to						
			Level 4 - Fly proof toilet is urgently needed to be repaired.				
			-Often toilet unavailable				
			-After filling the soil, some toilets need to be lifted up.				

		Level 1 HH No. 6 HH No. 12 HH No. 12
		Level 3HH No. 31Image: He control of the control of t
(6). Electricity	Improved ■* Same □ Worse □ *as last week	<u>Description</u> -Electricity comes regularly. -Electric poles and transformer are being supported with a good foundation. -There was a hole at an electric pole which was hit by a truck car, but the electric pole was renovated. <u>Photos</u>
		<image/>

Na	ltana	Condition	Description and D	hataa		
No 2	Item	Condition No. of	Description and P	notos		
2	House Construct -ion	houses not completed (2)	Description -HH No.5, the con again.	struction for kitchen	, toilet and water tank seems to be stopped	
3	Living	Description				
	Status of	(1) House ov				
	PAPs			re owned by PAPs (5	50)	
	(Sold		1)-2 No. of house that were sold (18)			
	house, renting,		ing condition (2)-1 No. of bouses where BABs live. (41)			
	etc.)		(2)-1 No. of houses where PAPs live (41)(2)-2 No. of houses where original PAPs lives do not live (22)			
	,		No. of houses when	-	· ·	
			p: See ANNEX.2			
4	Other issue	Other issue				
	(1). Drainag					
	condition for rain water i		ason has started.	wot		
	their		the compounds are No. of HHs	E WEL.	۱	
	compounds	Conditi		Previous week	1	
			condition	condition		
		Level 1	63	63	1	
		Level 2	5	5]	
		Level 3	0	0		
		Level 4	0	0]	
	Evaluation Criteria Level 1 -No mud and no standing water with their own drainage system in their compound				rainage system in their compound	

		Level 2					
		-No mud and no standing water in their compound Level 3					
		- Some or little mud and standing water in their compound					
		<i>Level 4</i> -A lot of mud and standing water in their compound					
		Photos					
HH No. 47 Level 1 HH No. 45 HH No. 45					vel 3		
4	(2) Plantation	HH No. 61					
			ir compounds,	ounds, the people planted shady trees, fruit trees, vegetables and floral			
		plants.	No. of HHs	Remarks	1		
		Type Shady tree	NO. 01 HHS	Albizzia, Indian almond, etc.	1		
			41	HH No. 2, 3, 14, 15,16, 17, 18, 19, 20, 23, 25, 26,			
				27, 32, 33, 39, 41, 44, 48, 58 and 65			
		Fruit tree	27	Banana, Mango, sugarcane, coconut, citrus, etc.			
				HH No.1, 2, 3, 4, 8, 9, 11, 17, 24, 25, 27, 29, 30,			
				34, 36, 37, 38, 39, 40, 41, 43, 45, 46, 47, 48, 65			
				and 67			
		Vegetable	11	Spices, peas, roselle, etc.			
			• -	HH No. 15, 23, 25, 38, 39, 40, 42,45, 58, 63 and 67			
		Floral plant	26	Many species.			
				HH No. 2, 9, 14, 15, 17, 18, 19, 21, 26, 27, 30, 31, 32, 33, 38, 39, 40, 41, 42, 43, 47, 48, 58, 59, 62			
				32, 33, 38, 39, 40, 41, 42, 43, 47, 48, 58, 59, 62 and 65			
		1 1		aliu UJ			

4	(3) Livestock	Description			
		-The people ar		en,	
		ducks, goats a			
		-Even though t			
		PAPs do not ke			
		relocation site their farms or		keep in	
		Туре	No. of HHs	Remarks	
		Cow	4	HH No. 1, 42, 47	
		Dia		and 54	-
		Pig Goat	- 3	- HH No.15, 47, 50	-
		Chicken and	18	HH No. 3, 4, 8, 12,	1
		ducks	_	14, 15, 20, 28, 30,	
				32, 41, 47, 50, 51,	
				52, 54, 56 and 62	
		<u>Photos</u>			
		A Martin Contraction		SI SI	
		SK STO	and the second s		A REAL PROPERTY AND A REAL PROPERTY A REAL PROPERTY AND A REAL PROPERTY A REAL PRO
		the state	SPIE .		
		A LAND	5 Million	. when the	formation and the second
			and the second second	· Lastation and	IT STATES THE PARTY OF THE

ANNEX.1

As of 20.11.2015

