Weekly Field Report

Surveyor: Zaw La


Date Visited: 28.6.2016

Time Visited: 13:30 to 14:30

Weather Condition: Sunny

The last time of heavy raining: - yesterday

No	Item	Condition	Description and Photos		
1	Condition o	of -			
	(1). Well	Improved□ Same®* Worse □ *as last week	Description & Photos: -See ANNEX.1 - Water from both of two wells is clean and can be used for drinking and living. The amount of water in both wells is also being increased during these days. There are four tube wells in the relocation site. Among them, one of the hand pump needs to be repaired, but people can get water from their own tube-wells, one open-well and the rest of two hand pumps.		
	(2).	Improved□	<u>Description</u>		
	Drainage Same Worse □ *as last week		There is some amount of water in the drainage canals due to the rain yesterday and some places of stream seem to be blocking at the moment. The stream along the drainage canal may need to be rehabilitated in order to improve the water-flow along the stream.		
			<u>Photos</u>		
			Near Well No. 1 Near HH No. 48		
			Near HH No. 1 Near HH No. 1		



(3). Road **Improved**

0*

Same □

Worse □ *as last week

-The roads are being dry and no problem for walking.









(4). Garbage Condition

Improved□

Same **©*** Worse □

Description

- People do not want to use garbage pit again.
- They do not like people to take washing clothes and showering near the well and therefore garbage pit was demolished and water storage tank has been constructed instead of it.
- -Trash from all houses will be collected by garbage truck biweekly until starting of the community fund.
- -There is a small vegetable planting field at the backside of Third Row where there were many trashes before the vegetable plantation was started.







N ltem o (5). Fly 1 proof toilet

Condition

Improved

⊙*

Same □

Worse □
*as last
week

Description

- -All of the fly proof toilets are used by people.
- -Almost all of the fly proof toilets made by wood or bamboo have been lifted up as shown in pictures below and are convenient to use. Some concrete toilets are still needed to be renovated. According to discussion with community people, they would like to repair the concrete toilets by themselves and requested for financial support. JET had already paid for it.

	No. of HHs		
Condition	This	Previous	
	week	week	
	condition	condition	
Level 1	50	50	
Level 2	17	17	
Level 3	0	0	
Level 4	0	0	
No Toilet	1	1	

<Evaluation Criteria>

Level 1

- Fly proof toilet is not needed to be repaired.
- -No/rarely toilet unavailable

Level 2

- Fly proof toilet is needed to be repaired.
- -Rarely toilet unavailable

Level 3

- -- Fly proof toilet is needed to be repaired.
- -Often toilet unavailable
- -As the result of filling the soil and also due to the heavy rain, some toilets are inconvenience to use.

Ι ουοί Λ

- Fly proof toilet is urgently needed to be repaired.

-Often toilet unavailable









(6). Electricity _

Same □

Worse □
*as last
week

Description

- -Electricity comes regularly.
- -Electric poles and transformer are being supported with a good foundation.
- -There was a hole at an electric pole which was hit by a truck car but the electric pole was renovated.

Photos







No Item Condition

Description and Photos

	Τ	l						
2	House	No. of	<u>Description</u>					
	Construct	houses not	-HH No.5, the construction for kitchen, toilet and water tank seems to be stopped					
	-ion	completed	again.					
		(2)	HH No. 5					
3	Living	Description	escription					
	Status of	(1) House ow	nership					
	PAPs		(1)-1 No. of house that are owned by PAPs (45)					
	(Sold		(1)-2 No. of house that were sold (23)					
	house,	(2) Living con	Living condition					
	renting,	(2)-1	(2)-1 No. of houses where PAPs live (37)					
	etc.)	(2)-2	(2)-2 No. of houses where original PAPs do not live (28)					
		(2)-3	(2)-3 No. of houses where nobody lives (3)					
		Location Map	cation Map: See ANNEX.2					
4	Other issue	!						
	(1). Drainag	ge <u>Description</u>	<u>on</u>					
	condition f	or						
	rain water in		No. of HHs					
	their	Conditio	n This week	Previous week				
	compound	5	condition	condition				
		Level 1	63	63				
		Level 2	5	5				
		Level 3	0	0				
		Level 4	0	0				
	Evaluation Criteria> Level 1 -No mud and no standing water with their own drainage system in their compound							
					system in their compound			
		Level 2			,,			
	-No mud and no standing water in their compound Level 3							

- Some or little mud and standing water in their compound

-A lot of mud and standing water in their compound

Level 4

<u>Photos</u>









4 (2) Plantation

Description

-In front of their compounds, the people planted shady trees, fruit trees, vegetables and floral plants.

Type	No. of HHs	Remarks
Shady tree	21	Albizzia, Indian almond, etc.
		HH No. 2, 3, 14, 15,16, 17, 18, 19, 20, 23, 25, 26,
		27, 32, 33, 39, 41, 44, 48, 58 and 65
Fruit tree	27	Banana, Mango, sugarcane, coconut, citrus, etc.
		HH No.1, 2, 3, 4, 8, 9, 11, 17, 24, 25, 27, 29, 30,
		34, 36, 37, 38, 39, 40, 41, 43, 45, 46, 47, 48, 65
		and 67
Vegetable	11	Spices, peas, roselle, etc.
		HH No. 15, 23, 25, 38, 39, 40, 42,45, 58, 63 and 67
Floral plant	26	Many species.
		HH No. 2, 9, 14, 15, 17, 18, 19, 21, 26, 27, 30, 31,
		32, 33, 38, 39, 40, 41, 42, 43, 47, 48, 58, 59, 62
		and 65









4 (3) Livestock

Description

-The people are raising chicken, ducks, goats, pigs and cows.
-Even though they have cows, some PAPs do not keep their cows in relocation site instead they keep in their farms or other places.

Туре	No. of HHs	Remarks
Cow	4	HH No. 1, 42, 47
		and 54
Pig	1	HH No. 48
Goat	3	HH No.15, 47, 50
Chicken and	18	HH No. 3, 4, 8, 12,
ducks		14, 15, 20, 28, 30,
		32, 41, 47, 50, 51,
		52, 54, 56 and 62

<u>Photos</u>





ANNEX.1 As of 28.6.2016

