Weekly Field Report

Surveyor: Zaw La


Date Visited: 13.6.2016

Time Visited: 13:30 to 14:30

Weather Condition: Sunny

The last time of heavy raining: - yesterday

No	Item	Condition	Description and Photos				
1	Condition o	of -					
	(1). Well	Improved☐ Same©* Worse ☐ *as last week	Description & Photos: -See ANNEX.1 - Water from both of two wells is clean and can be used for drinking and living. The amount of water in both wells is also being increased during these days. There are four tube wells in the relocation site. Among them, one of the hand pump needs to be repaired, but people can get water from their own tube-wells, the two open-wells and the rest of two hand pumps.				
	(2). Drainage	Improved□ Same • Worse □ *as last week	Description There is almost full amount of water in the drainage canals due to heavy rain yesterday and some places of stream seem to be blocking at the moment. The stream along the drainage canal may need to be rehabilitated in order to improve the waterflow along the stream.				
			Near Well No. 1 Near HH No. 48				
			Near HH No. 1 Near HH No. 1				







Washing clothes and taking bath place



N Item o (5). Fly proof toilet

Condition

Improved **©***

Same □

Worse □
*as last
week

Description

- -All of the fly proof toilets are used by people.
- -Almost all of the fly proof toilets made by wood or bamboo have been lifted up as shown in pictures below and are convenient to use. Some concrete toilets are still needed to be renovated. According to discussion with community people, they would like to repair the concrete toilets by themselves and requested for financial support. JET had already paid for it.

	No. of HHs			
Condition	This	Previous		
	week	week		
	condition	condition		
Level 1	50	50		
Level 2	17	17		
Level 3	0	0		
Level 4	0	0		
No Toilet	1	1		

<Evaluation Criteria>

Level 1

- Fly proof toilet is not needed to be repaired.
- -No/rarely toilet unavailable

Level 2

- Fly proof toilet is needed to be repaired.
- -Rarely toilet unavailable

Level 3

- -- Fly proof toilet is needed to be repaired.
- -Often toilet unavailable
- -As the result of filling the soil and also due to the heavy rain, some toilets are inconvenience to use.

Ι ουρί Λ

- Fly proof toilet is urgently needed to be repaired.

-Often toilet unavailable









(6). Electricity

Improved

0*

Same □

Worse □
*as last
week

Description

- -Electricity comes regularly.
- -Electric poles and transformer are being supported with a good foundation.
- -There was a hole at an electric pole which was hit by a truck car but the electric pole was renovated.

Photos







	Г.,	_	11.1	_					
No	Item		ndition	Description and Photos					
2	House		. of	<u>Description</u>					
	Construct		uses not			, toilet and water tank seems to be stopped			
	-ion		mpleted	again.					
		(2)							
				НН	HH No. 5				
					MINUTES TO THE PARTY OF THE PAR	主义于到了			
							76		
3	Living	De	escription						
	Status of	(1)	1) House ownership						
	PAPs		(1)-1 No. of house that are owned by PAPs (45)						
	(Sold		(1)-2 No. of house that were sold (23)						
	house,	(2)	Living condition						
	renting,		(2)-1	(2)-1 No. of houses where PAPs live (37)					
	etc.)			(2)-2 No. of houses where original PAPs do not live (28)					
				(2)-3 No. of houses where nobody lives (3)					
	_		cation Map: See ANNEX.2						
4	Other issue								
	(1). Drainag								
	condition for				1				
	rain water in their Condition		'n	No. of HHs This week	Previous week				
	compounds		Conditio)	condition	condition			
	Compounds		Level 1		63	63	1		
			Level 2		5	5			
			Level 3		0	0			
			Level 4		0	0			
					<u> </u>	1 -			
			<evaluation criteria=""></evaluation>						
		Level 1							
		-No mud and no standing water with their own drainage system in their compound					rainage system in their compound		
			Level 2						
			-No mud and no standing water in their compound						
			Level 3						
		- Some or little mud and standing water in their compound							
			Level 4						

-A lot of mud and standing water in their compound

<u>Photos</u>









4 (2) Plantation

Description

-In front of their compounds, the people planted shady trees, fruit trees, vegetables and floral plants.

Type	No. of HHs	Remarks
Shady tree	21	Albizzia, Indian almond, etc.
		HH No. 2, 3, 14, 15,16, 17, 18, 19, 20, 23, 25, 26,
		27, 32, 33, 39, 41, 44, 48, 58 and 65
Fruit tree	27	Banana, Mango, sugarcane, coconut, citrus, etc.
		HH No.1, 2, 3, 4, 8, 9, 11, 17, 24, 25, 27, 29, 30,
		34, 36, 37, 38, 39, 40, 41, 43, 45, 46, 47, 48, 65
		and 67
Vegetable	11	Spices, peas, roselle, etc.
		HH No. 15, 23, 25, 38, 39, 40, 42,45, 58, 63 and 67
Floral plant	26	Many species.
		HH No. 2, 9, 14, 15, 17, 18, 19, 21, 26, 27, 30, 31,
		32, 33, 38, 39, 40, 41, 42, 43, 47, 48, 58, 59, 62
		and 65









4 (3) Livestock

Description

-The people are raising chicken, ducks, goats, pigs and cows.
-Even though they have cows, some PAPs do not keep their cows in relocation site instead they keep in their farms or other places.

Туре	No. of HHs	Remarks	
Cow	4	HH No. 1, 42, 47	
		and 54	
Pig	1	HH No. 48	
Goat	3	HH No.15, 47, 50	
Chicken and	18	HH No. 3, 4, 8, 12,	
ducks		14, 15, 20, 28, 30,	
		32, 41, 47, 50, 51,	
		52, 54, 56 and 62	

<u>Photos</u>





ANNEX.1

