Weekly Field Report

Surveyor: Zaw La

Date Visited: 20.5.2016

Time Visited: 10:15 to 11:15

Weather Condition: Sunny
The last time of heavy raining: -

No	Item	Condition	Description and Photos
1	Condition of	of -	
	(1). Well	Improved□ Same• *Worse□ *as last week	Description & Photos: -See ANNEX.1 - Water from both of two wells is clean and can be used for drinking and living. But the amount of water in both wells is being decreased during these days. There are four tube wells in the relocation site. Among them, one of the hand pumps needs to be repaired, but people can get water from their own tube-wells, the two open-wells and the rest of two hand pumps.
	(2). Drainage	Improved□ Same ©* Worse □ *as last week	Description There is almost no water in the drainage canals. The stream along the drainage canal may need to be rehabilitated in coming summer period in order to improve the water-flow along the stream. Photos
			Near Well No. 1 Near HH No. 48
			Near HH No. 1 Near garbage pit



(3). Road

Improved

Same □

0*

Worse □
*as last
week

Description

-The roads are being dry and no problem for walking.

Photos









(4). Garbage Condition

Improved□ Same **©***

Worse □

Description

- People do not want to use garbage pit again.
- They do not like people to take washing clothes and showering near the well and therefore garbage pit was demolished and water storage tank has been constructed instead of it.
- -Trash from all houses will be collected by garbage truck biweekly until starting of the community fund.
- -There is a small vegetable planting field at the backside of Third Row where there were many trashes before the vegetable plantation was started.







N ltem o (5). Fly 1 proof toilet

Condition

Same □

Worse □
*as last
week

Description

- -All of the fly proof toilets are used by people.
- -Almost all of the fly proof toilets made by wood or bamboo have been lifted up as shown in pictures below and are convenient to use. Some concrete toilets are still needed to be renovated. According to discussion with community people, they would like to repair the concrete toilets by themselves and requested for financial support. JET had already paid for it.

	No. of HHs			
Condition	This	Previous		
	week	week		
	condition	condition		
Level 1	50	50		
Level 2	17	17		
Level 3	0	0		
Level 4	0	0		
No Toilet	1	1		

<Evaluation Criteria>

Level 1

- Fly proof toilet is not needed to be repaired.
- -No/rarely toilet unavailable

Level 2

- Fly proof toilet is needed to be repaired.
- -Rarely toilet unavailable

Level 3

- -- Fly proof toilet is needed to be repaired.
- -Often toilet unavailable
- -As the result of filling the soil and also due to the heavy rain, some toilets are inconvenience to use.

Level 4

- Fly proof toilet is urgently needed to be repaired.
- -Often toilet unavailable









(6). Electricity Improved

*

Same □

Worse □
*as last
week

Description

- -Electricity comes regularly.
- -Electric poles and transformer are being supported with a good foundation.
- -There was a hole at an electric pole which was hit by a truck car but the electric pole was renovated.

Photos







N 1 -		6.		5	data a salaba			
No	Item		ndition	Description and Photos				
2	House		o. of					
	Construct		uses not			ruction for kitchen,	toilet and water tank seems to be stopped	
	-ion		mpleted	again.				
		(2)						
				HH No. 5				
						TO DE 1		
3	Living	De	escription escription					
	Status of		House ow	nershi	ip			
	PAPs	, ,			•	e owned by PAPs (4	5)	
	(Sold		(1)-2 No. of house that were sold (23)					
	house,	(2)	2) Living condition					
	renting,		(2)-1 No. of houses where PAPs live (37)					
	etc.)		(2)-2	No. of	houses where	original PAPs do no	ot live (28)	
			(2)-3	(2)-3 No. of houses where nobody lives (3)				
		Lo	cation Map	ation Map: See ANNEX.2				
4	Other issue							
	(1). Drainag							
	condition fo							
	rain water i	n			No. of HHs	1		
	their		Conditio	n	This week	Previous week		
	compounds	5			condition	condition		
			Level 1		63	63		
			Level 2		5	5		
			Level 3		0	0		
			Level 4		0	0		
			- دامادی	tion C	ritaria>			
		<evaluation criteria=""></evaluation>						
		Level 1 No mud and no standing water with their own drainage system in their compound						
		-No mud and no standing water with their own drainage system in their compound Level 2					Tamage system in their compound	
		-No mud and no standing water in their compound					nd	
		Level 3						
	- Some or little mud and standing water in their compound							
	Level 4							
	-A lot of mud and standing water in their compound							
	A though the desired by the termination of the term							

Photos









4 (2) Plantation

Description

-In front of their compounds, the people planted shady trees, fruit trees, vegetables and floral plants.

Type	No. of HHs	Remarks		
Shady tree 21		Albizzia, Indian almond, etc.		
		HH No. 2, 3, 14, 15,16, 17, 18, 19, 20, 23, 25, 26,		
		27, 32, 33, 39, 41, 44, 48, 58 and 65		
Fruit tree	27	Banana, Mango, sugarcane, coconut, citrus, etc.		
		HH No.1, 2, 3, 4, 8, 9, 11, 17, 24, 25, 27, 29, 30,		
		34, 36, 37, 38, 39, 40, 41, 43, 45, 46, 47, 48, 65		
		and 67		
Vegetable	11	Spices, peas, roselle, etc.		
		HH No. 15, 23, 25, 38, 39, 40, 42,45, 58, 63 and 67		
Floral plant	26	Many species.		
		HH No. 2, 9, 14, 15, 17, 18, 19, 21, 26, 27, 30, 31,		
		32, 33, 38, 39, 40, 41, 42, 43, 47, 48, 58, 59, 62		
		and 65		









(3) Livestock 4

<u>Description</u>
-The people are raising chicken, ducks, goats, pigs and cows. -Even though they have cows, some PAPs do not keep their cows in relocation site instead they keep in their farms or other places.

Туре	No. of HHs	Remarks
Cow	4	HH No. 1, 42, 47
		and 54
Pig	1	HH No. 48
Goat	3	HH No.15, 47, 50
Chicken and	18	HH No. 3, 4, 8, 12,
ducks		14, 15, 20, 28, 30,
		32, 41, 47, 50, 51,
		52, 54, 56 and 62

Photos





ANNEX.1 As of 20.5.2016 This well is repaired and now clean water can be used for drinking and living. Nevertheless, water in the well is being reduced at the moment and does not Hand pump isn't functioned. enough to use. This hand pump is functioned very The buffer has repaired and water can well. Water is clean and people be get again. nearby are using this hand pump for 2) drinking and living. 65 64 63 62 The water amount 47 60 59 46 58 in this well is also 43 57 56 being reduced at 54 53 the moment. 52 39 38 51 37 50 36 35 34 6 33 | 32 31 30 11 29 12 28 13 27 14 15 25 16 17 18 19 20 21 22 | 23 The buffer of the hand pump needs to be changed. But, people living nearby would like to use water from their owned pumps instead of this hand pump. This hand pump is functioned very WALL TO A well. Water is clean and people living nearby are using this hand **Closed Well** pump. Moreover water filter tank New Well (Hand pump) has been set up beside the hand pump for removing the smell of **Open Well** iron. There is no smell of iron and people enjoy water for drinking **Hand Pump** and living use. **Private Well**