# **Weekly Field Report**

Surveyor: Zaw La

Date Visited: 25.2.2016

Time Visited: 10:30 to 11:30

Weather Condition: Sunny
The last time of heavy raining: -

No	Item	Condition	Description and Photos		
1	Condition of	of -			
	(1). Well	Improved□ Same• *Worse□  *as last week	Description & Photos: -See ANNEX.1 - Water from both of two wells are clean and enough to use for drinking and living. There are four tube wells in the relocation site. Among them, two of the hand pumps need to be repaired, but people can get water from their own tube-wells, the rest of two hand pumps and the two wells.		
	(2). Drainage	Improved□ Same ■* Worse □ *as last week	-Water level in the drainage canals are the same as last week because there was no rain. The stream along the drainage canal may need to be rehabilitated in coming summer period in order to improve the water-flow along the stream.  Photos		
			Near Well No. 1  Near HH No. 48		
			Near HH No. 1  Near garbage pit		









## N ltem o (5). Fly proof toilet

# Condition

Improved

**©**\*

Same □

Worse □
\*as last
week

## **Description**

- -All of the fly proof toilets are used by people.
- -Almost all of the fly proof toilets made by wood or bamboo have been lifted up as shown in pictures below and are convenient to use. Some concrete toilets are still needed to be renovated. According to discussion with community people, they would like to repair the concrete toilets by themselves and requested for financial support. JET had already paid for it.

	No. of HHs		
Condition	This	Previous	
	week	week	
	condition	condition	
Level 1	50	50	
Level 2	17	17	
Level 3	0	0	
Level 4	0	0	
No Toilet	1	1	

## <Evaluation Criteria>

#### Level 1

- Fly proof toilet is not needed to be repaired.
- -No/rarely toilet unavailable

### Level 2

- Fly proof toilet is needed to be repaired.
- -Rarely toilet unavailable

## Level 3

- -- Fly proof toilet is needed to be repaired.
- -Often toilet unavailable
- -As the result of filling the soil and also raining, some toilets are inconvenience to use.

## Level 4

- Fly proof toilet is urgently needed to be repaired.
- -Often toilet unavailable

-After filling the soil, some toilets need to be lifted up.









(6). Electricity Improved

o\*

Same □

Worse □
\*as last
week

## Description

- -Electricity comes regularly.
- -Electric poles and transformer are being supported with a good foundation.
- -There was a hole at an electric pole which was hit by a truck car, but the electric pole was renovated.

**Photos** 







	ı								
Na	Itam	Condition	Description and D	lhotos					
No 2	Item		Description and Photos						
2 House No. of <u>Description</u> Construct houses not HH No.5, the construction for kitchen, toilet and water tank sooms to									
	Construct   houses not   -HH No.5, the construction for kitchen, toilet and water tank seems to be   -ion   completed   again.								
	-1011	(2)	red again.						
		(2)	HH No. 5						
			TITT NO. 5						
			1000年						
			ANASTE						
3	Living	Description	WAR CONTRACTOR						
3	Status of	(1) House ow	nershin						
	PAPs		•	are owned by PAPs (47)					
	(Sold		No. of house that v	,					
	house,	(2) Living con							
	renting,		No. of houses whe	ere PAPs live (38)					
	etc.)		(2)-2 No. of houses where original PAPs do not live (22)						
		(2)-3	No. of houses whe	ere nobody lives (6)					
			o: See ANNEX.2						
4	Other issue								
	(1). Drainag		<u>on</u>						
	condition fo								
	rain water i		No. of HHs	Decision and					
	their compounds	Condition	n This week condition	Previous week condition					
	Compounds	Level 1	63	63					
		Level 2	5	5					
		Level 3	0	0					
		Level 4	0	0					
		2070.1							
		<evaluat< th=""><th>tion Criteria&gt;</th><th></th></evaluat<>	tion Criteria>						
		Level 1							
	-No mud and no standing water with their own drainage system in their compound								
	Level 2								
	-No mud and no standing water in their compound								
	Level 3								
	- Some or little mud and standing water in their compound  Level 4								

-A lot of mud and standing water in their compound

# **Photos**









#### (2) Plantation 4

<u>Description</u>
-In front of their compounds, the people planted shady trees, fruit trees, vegetables and floral plants.

J- 10111001	1	
Type	No. of HHs	Remarks
Shady tree	21	Albizzia, Indian almond, etc.
		HH No. 2, 3, 14, 15,16, 17, 18, 19, 20, 23, 25, 26,
		27, 32, 33, 39, 41, 44, 48, 58 and 65
Fruit tree	27	Banana, Mango, sugarcane, coconut, citrus, etc.
		HH No.1, 2, 3, 4, 8, 9, 11, 17, 24, 25, 27, 29, 30,
		34, 36, 37, 38, 39, 40, 41, 43, 45, 46, 47, 48, 65
		and 67
Vegetable	11	Spices, peas, roselle, etc.
		HH No. 15, 23, 25, 38, 39, 40, 42,45, 58, 63 and 67
Floral plant	26	Many species.
		HH No. 2, 9, 14, 15, 17, 18, 19, 21, 26, 27, 30, 31,
l		32, 33, 38, 39, 40, 41, 42, 43, 47, 48, 58, 59, 62
		and 65









## 4 (3) Livestock

## **Description**

- -The people are raising chicken, ducks, goats and cows.
- -Even though they have cows, some PAPs do not keep their cows in relocation site instead they keep in their farms or other places.

Туре	No. of HHs	Remarks
Cow	4	HH No. 1, 42, 47
		and 54
Pig	-	-
Goat	3	HH No.15, 47, 50
Chicken and	18	HH No. 3, 4, 8, 12,
ducks		14, 15, 20, 28, 30,
		32, 41, 47, 50, 51,
		52, 54, 56 and 62

# <u>Photos</u>





ANNEX.1 As of 25.2.2016 This well is repaired and now clean water can be used for drinking and living. Hand pump isn't functioned. This hand pump is functioned very The buffer has been broken at the well. Water is clean and people moment and it needs to be repaired. nearby are using this hand pump for 2) drinking and living. 65 64 63 62 This well is also 46 45 44 47 60 59 58 repaired and now 57 56 43 ready to get clean 54 53 water for drinking 52 39 38 51 and living use. 37 36 34 6 33 32 31 30 11 29 12 28 13 14 15 25 16 17 18 19 20 21 The buffer of the hand pump needs to be change. Therefore, people living nearby are using water from their owned pump at the moment. This hand pump is functioned very well. Water is clean and people living nearby are using this hand **Closed Well** pump. Moreover water filter tank New Well (Hand pump) has been set up beside the hand pump for removing the smell of **Open Well** iron. There is no smell of iron and people enjoy water for drinking **Hand Pump** and living use. **Private Well**