<u>Surveyor: Sithu Nyein</u> Date Visited: 18.8.2014 Time Visited: 10:00 to 12:30

Weather Condition: Sunny and partly cloudy The last time of heavy raining: 15.8.2014

No	Item	Condition	Description and Photos
1	Condition of -		
	(1). Well	Improved □ Same ■* Worse □ *as good as last week	Description & Photos: See ANNEX.1
	(2). Drainage	Improved	Description
	(_)	Same 🗆	Water in the drainage canal is becoming lower than last week.
		Worse 🗆	Photos Image: State of the stateoo the state of the state
	(3). Road	Improved □ Same © * Worse □ *as good as last week	<u>Description</u> All roads are in good condition There are some puddles and partly muddy areas but the roads are almost dried and no problem for traffic as a whole. <u>Photos</u>

No	Item	Condition	Description	n and Photos
1	(4). Garbage Pit	Improved □ Same □ Worse 回	<u>Description</u> Garbage pit is surrounded by water People are not using garbage pit	Photo
	(5). Septic Tank	Improved Same □ Worse □	Description-Some of the septic tanks arenearly full by waterMost of septic tanks are in goodcondition for use.ConditionNo. of HHsVery Good42Good21Bad0Very Bad0No Toilet5 <evaluation criteria="">Very Good-No need to repair septic tank-No/rarely toilet availableGood-Need to repair septic tank-Need to repair septic tank-Need to repair septic tank-Need to repair septic tank-Need to repair septic tank-Often toilet unavailableVery Bad-Need to repair septic tank-Often toilet unavailableVery Bad-Need to repair urgently septic tank-Often toilet unavailableVery Bad-Need to repair urgently septic tank-Often toilet unavailable</evaluation>	Photos HH No. 7 Very Good HH No. 65 Good
	(6). Electricity	Improved □ Same © * Worse □ *as good as last week	<u>Description</u> -Electricity is coming regularly	are in good foundation by concrete else.

No	ltem	Condition	Description and Photos
2	House Construction	No. of houses not completed (2)	Description -HH No.1 doesn't have ladder and nobody is living -In HH No.5, the construction for kitchen, toilet and water tank seems stopped. Nobody is living. -In HH No.5, sun shade of this house is collapsed due to wind. Wind is not so strong but the quality of the sun shade is not so good enough. Photos HH No.1 HH No.1 HH No.5 HH No.5 HH No.5 HH No.5 HH No.5
3	Living Status of PAPs (Sold house, renting, etc.)	Description (1) No. of sold house (19) (1)-1 No. of sold house where nobody lives (3) (1)-2 No. of sold house where not original PAPs lives (16) (2) No. of houses unknown if sold or not (11) (2)-1 No. of houses unknown if sold or not, and nobody lives (4) (2)-2 No. of houses unknown if sold or not, and not original PAPs lives (7) (3) No. of houses where original PAPs live (38) Location Map: See ANNEX.2	

No	Item	Description and Photos		
4	Other issues			
	(1). Flood condition	<u>Description</u> -It is not severer condition during this week because it is less heavy raining. -But there are some puddles and muddy areas in most of the compounds.		
		Condition No. of HHs Very Good 6 Good 17 Bad 28 Very Bad 17 Evaluation Criteria> Very Good		
		HH No. 47 HH No. 47 Very Good		
		HH No. 2 Bad		

No	ltem	Description and Photos
4	(2) Garbage	Description -People threw the garbage in the backside of their compound over the fence especially who live in third row. -Some people put the garbage near electrical transformer so this area become dirtier than last week -Garbage are also gathering in the drainage canal Photos
		Garbage at the backside of HH No.49
		Near transformer Drainage canal near HH No.48 Orainage construction
5	Remarks	
	being shot wit released as U I	(HH No.11) and Ko Zaw Myo Htet (HHNo.21) have been arrested by police because of h stones to HH No.37 after they drunk. Today morining(18.8.2014) these two men are Myint Thu and other community heads made an insurance for them. For now, both iled not to go for a cause.

ANNEX.1

Updated 18.8.2014

