
Bi weekly Field Report

SurveyorZaw LaDate visited17 Feb 2020Time visited10:45 am

Weather Condition <u>Sunny</u> The last time of heavy raining:

No	Item	Condition	Narrative Description and Photos	
1	(1.1) Water Supply System	Improved □ Same ■* Worse □ *as last week	Narrative Description Water distribution system has been sup zone B resettled families. The new wel line and its necessary instruments beca previous well includes iron hydroxide a the iron removal tank. The current wate iron hydroxide and yellowish mud are	Il was drilled and installed the pipe use the underground water of the and yellowish mud that clogged in er condition is quite good and no
			Photos	
			Water from ground water tank	Pipe line distribution water to houses

1 (1.2) Well Improved: Sinc ■*	No	Item	Condition	Narrative Description and Photos		
(2) Improveding Same ** *as last week *as last week - There is no water in the drainage canals at the moment. Photos - There is no water in the drainage canals at the moment. *as last week - There is no water in the drainage canals at the moment. The drain at the corner of Main Road A and B - The exit of the drain at the corner of Site village road and 2 nd street The exit of the drain at the corner of Site village road and 3 nd street - The exit of the drain at the corner of Site village road and 3 nd street (3) Road Improveding - All the roads are dry and no problem for walking.	1	(1.2) Well	Same ■ * Worse □	living. There are eleven tube wells in the relocation site. Residents u the water basically from the pipeline distribution system so that t frequency of water usage from the tube wells is very low. To susta the good condition of the tube wells, the leg pumps were kept as	ise the ain	
Drainage Same T* Worse □ *as last week Photos The drain at the corner of Main Road A and B The exit of the drain at the corner of Site village road and 2 nd street The exit of the drain at the corner of Main Road A and B The exit of the drain at the corner of Site village road and 2 nd street The exit of the drain at the corner of Site village road and 3 nd street The exit of the drain at the corner of Site village road and 3 nd street (3) Road Improved□ Same T* - All the roads are dry and no problem for walking.				Open Well No. 1	The North W	
Same •*			Same © * Worse □	PhotosImage: Photos <td></td>		
		(3) Road	Same ■ *			



		T th Street	Site Village Road
(4) Garbage Condition	Improved□ Same © * Worse □ * <i>as last week</i>	of each road until the end of Apri are kept by the community leader of well number one of main road	e bins are provided. been provided and placed at the corner l. After April 2018, all the garbage bins of PAPs in the communal compound B. But starting from October, the hicipal office came and collected by
		Rubbishes in the creek near 1st street	Rubbishes in the creek near 2nd street
		The soil was filled near the creek of Main Road C in March	The soil was filled near the creek of 6 th Street in March

(5) Fly proof toilet	Improved□ Same © * Worse □ *as last week	 All of the fly proof toilets are used by the residents. All of the toilets are repaired by the following procedures; Installation the extra septic tanks beside the original The pipe line system is installed from the extra tank to the ditch to flow the liquid out. The toilet renovation plan was successfully done and there is no problem at the moment.			
		Condition Level 1 Level 2 Level 3	No. of 1 This week condition 91 0 0	HHs Previous week condition 91 0 0	
		Level 4 No Toilet	0	0	
		 Example 1 (1) Evaluation Criteria> <i>Level 1</i> Fly proof toilet is not needed to be repaired. No/rarely toilet unavailable <i>Level 2</i> Fly proof toilet is needed to be repaired. Rarely toilet unavailable <i>Level 3</i> Fly proof toilet is needed to be repaired. Often toilet unavailable As the result of filling the soil and also due to the heavy rain, some toilets are inconvenience to use. <i>Level 4</i> Fly proof toilet is urgently needed to be repaired. Often toilet unavailable 			
		House No. 4		House No. 50	
		House No.		House No. 87	

	(6) Electricity	Improved□ Same © * Worse □ *as last week	 Residents get the electricity regularly. Electric poles and transformer are being supported with the good foundations. There are some pieces of wood under an electric pole of main road B and it's needed to clean up. Photos 			
			Transformer No. 1	Transformer No. 2		
			Transformer No. 3	Electric poles of Main Road B and Main Road C		
No	Item	Condition	Description	and Photos		
No 2	Item (1)House Construct- ion	Condition No. of houses which are not completed (4)	 In plot No.9 and 10, three houses are owned by father and son. The are needed to be carried on. 	that are planned to build as the plots e second floors of these three houses on for the first floor has been finished		
	(1)House Construct-	No. of houses which are not	 In plot No.9 and 10, three houses are owned by father and son. The are needed to be carried on. Plot No. 66, the house construction 	that are planned to build as the plots e second floors of these three houses on for the first floor has been finished		
	(1)House Construct-	No. of houses which are not	 In plot No.9 and 10, three houses are owned by father and son. The are needed to be carried on. Plot No. 66, the house construction and the second floor is still needed 	that are planned to build as the plots e second floors of these three houses on for the first floor has been finished		

3	Other Issues				
	(1). Drainage condition for	Description			
	rain water in the compounds				
			No. of HHs		
		Condition	This week	Previous	
		T 11	condition	condition	
		Level 1	89	89	
		Level 2	2	2	
		Level 3			
		Level 4			
				er with their o	wn drainage system in their
		compound <i>Level 2</i> -No mud and n	o standing wate	er in their com	pound
		Level 3			
			mud and stand	ing water in tl	heir compound
		Level 4	1		
		-A lot of mud a	and standing wa	ter in their co	mpound
		<u>Photos</u>			
		Level 1 House No. 3			Level 2 House No. 19
		Level 3 House No. 6	4		Level 4 Automation of the second seco
		Level 3 House No. 7	75		Level 4 House No. 88

(2) Plantation		- In front of the compounds, the shady trees, fruit trees, flowering plants and vegetables are being planted.			
	Description				
	- In front of t and vegetal			trees, fruit trees, flowering plants	
	Туре	No. of HHs		Remarks	
	Shade tree	15		ian almond, Neem tree, etc. 40, 43, 48, 51, 57, 59, 61, 62, 67, 7, 85	
	Fruit tree	37	and jack fruit HH No. 3, 15 37, 40, 41, 48	5, 17, 20,21, 23, 28, 30, 31, 32, 34 3, 51, 52, 55, 57, 58, 59, 61, 62,	
	Vegetables	20	Chili, tomato basils, eggpla HH No. 12, 1	7, 21, 41, 49, 58, 59, 61, 62, 63,	
	Flowering plant	31	Jasmine, poir HH No. 3, 5, 22, 23, 29, 30	1, 72, 73, 77, 82, 85, 86 Isettia, orchid, kiss me quick, etc. 6, 8, 10, 12, 13, 14, 17, 20, 21, 0, 31, 32, 46, 48, 58, 59, 61, 62, 0, 72, 77, 78, 86	
	Photos,			, , , ,	
(3) Livestock	Description -The chicken, go	poses and d	ucks are being	raised	
	Type Chicken	No. of H	Hs Remarks		
i i	Chicken	0	HH No. 59, 67, 7	13, 14, 21, 8	
	Goose	2	HH No. 4		

