





























Surveyor Zaw La
 Date visited 6 Aug 2020
 Time visited 15:00 pm

Weather Condition Cloudy
 The last time of heavy raining:

| No | Item | Condition | Narrative Description and Photos |
|----|------------------------------------|---|---|
| 1 | (1.1) Water Supply System | Improved <input type="checkbox"/> Same <input checked="" type="checkbox"/> * Worse <input type="checkbox"/> <i>*as last week</i> | <p><u>Narrative Description</u></p> <p>Water distribution system has been supporting ninety household of the zone B resettled families. The new well was drilled and installed the pipe line and its necessary instruments because the underground water of the previous well includes iron hydroxide and yellowish mud that clogged in the iron removal tank. The current water condition is quite good and no iron hydroxide and yellowish mud are found.</p> <p><u>Photos</u></p> <div style="display: flex; flex-wrap: wrap;"> <div style="width: 50%; text-align: center;">  </div> <div style="width: 50%; text-align: center;">  </div> <div style="width: 50%; text-align: center;">  </div> <div style="width: 50%; text-align: center;">  </div> <div style="width: 50%; text-align: center;">  <p>Water from ground water tank</p> </div> <div style="width: 50%; text-align: center;">  <p>Pipe line distribution water to houses</p> </div> </div> |

| No | Item | Condition | Narrative Description and Photos |
|----|--------------|---|---|
| 1 | (1.2) Well | Improved <input type="checkbox"/> Same <input checked="" type="checkbox"/> * Worse <input type="checkbox"/> <i>*as last week</i> | <p>– Water from two open-wells is clean enough to use for drinking and living. There are eleven tube wells in the relocation site. Residents use the water basically from the pipeline distribution system so that the frequency of water usage from the tube wells is very low. To sustain the good condition of the tube wells, the leg pumps were kept and covered the PVC pipes with the caps till the residents use.</p> <div style="display: flex; justify-content: space-around;"> <div style="text-align: center;">  <p>Open Well No. 1</p> </div> <div style="text-align: center;">  <p>Open Well No. 2</p> </div> </div> |
| | (2) Drainage | Improved <input type="checkbox"/> Same <input checked="" type="checkbox"/> * Worse <input type="checkbox"/> <i>*as last week</i> | <p>– There is no water in the drainage canals at the moment.</p> <p>Photos</p> <div style="display: grid; grid-template-columns: 1fr 1fr; gap: 5px;"> <div style="text-align: center;">  <p>The drain at the corner of Main Road A and B</p> </div> <div style="text-align: center;">  <p>The exit of the drain at the corner of Site village road and 2nd street</p> </div> <div style="text-align: center;">  <p>The exit of the drain at the corner of Site village road and 3rd street</p> </div> <div style="text-align: center;">  <p>The exit of the drain at the corner of Site village road and Main Road C</p> </div> </div> |
| | (3) Road | Improved <input type="checkbox"/> Same <input checked="" type="checkbox"/> * Worse <input type="checkbox"/> <i>*as last week</i> | <p>– Some roads are found with small ponds due to the rain in these days but no problem for walking.</p> <p>Photos</p> |

| | | | | |
|--|--|--|--|--|
| | | |  <p>Main Road - B</p> |  <p>1st Street</p> |
| | | |  <p>2nd Street Upper Block</p> |  <p>2nd Street Lower Block</p> |
| | | |  <p>3rd Street Upper Block</p> |  <p>3rd Street Lower Block</p> |
| | | |  <p>4th Street Upper Block</p> |  <p>4th Street Lower Block</p> |
| | | |  <p>5th Street</p> |  <p>6th Street</p> |

| | | | | |
|-----------------------------|---|--|---|---|
| | | |  <p>7th Street</p> |  <p>Site Village Road</p> |
| (4) Garbage Condition | Improved <input type="checkbox"/> Same <input checked="" type="checkbox"/> * Worse <input type="checkbox"/> <i>*as last week</i> | <ul style="list-style-type: none"> - The rubbish was dumped at the creek side and even in front of the houses before the enough garbage bins are provided. - Total fourteen garbage bins have been provided and placed at the corner of each road until the end of April. After April 2018, all the garbage bins are kept by the community leader of PAPs in the communal compound of well number one of main road B. But starting from October, the garbage truck from township municipal office came and collected by giving its alarm along the Main Road B. <p>Photos</p> |  <p>Rubbishes in the creek near 1st street</p> |  <p>Rubbishes in the creek near 2nd street</p> |
| | | |  <p>The soil was filled near the creek of Main Road C in March</p> |  <p>The soil was filled near the creek of 6th Street in March</p> |

(5) Fly proof toilet

Improved
 Same *
 Worse
 *as last week

- All of the fly proof toilets are used by the residents.
- All of the toilets are repaired by the following procedures;
 - Installation the extra septic tanks beside the original
 - The pipe line system is installed from the extra tank to the ditch to flow the liquid out.

The toilet renovation plan was successfully done and there is no problem at the moment.

| Condition | No. of HHs | |
|-----------|---------------------|-------------------------|
| | This week condition | Previous week condition |
| Level 1 | 91 | 91 |
| Level 2 | 0 | 0 |
| Level 3 | 0 | 0 |
| Level 4 | 0 | 0 |
| No Toilet | 0 | 0 |

<Evaluation Criteria>

Level 1

- Fly proof toilet is not needed to be repaired.
- No/rarely toilet unavailable

Level 2

- Fly proof toilet is needed to be repaired.
- Rarely toilet unavailable

Level 3

- Fly proof toilet is needed to be repaired.
- Often toilet unavailable
- As the result of filling the soil and also due to the heavy rain, some toilets are inconvenience to use.

Level 4

- Fly proof toilet is urgently needed to be repaired.
- Often toilet unavailable

Photos



House No. 46







House No. 50












House No. 80







House No. 87

| | | | | |
|--------------------|---|--|---|---|
| (6) Electricity | Improved <input type="checkbox"/> Same <input checked="" type="checkbox"/> * Worse <input type="checkbox"/> <i>*as last week</i> | <ul style="list-style-type: none"> – Residents get the electricity regularly. – Electric poles and transformer are being supported with the good foundations. <p>Photos</p> |  <p>Transformer No. 1</p> |  <p>Transformer No. 2</p> |
| | | |  <p>Transformer No. 3</p> |  <p>Electric poles of Main Road B and Main Road C</p> |

| No | Item | Condition | Description and Photos | |
|----|-----------------------|---|---|--|
| 2 | (1)House Construction | No. of houses which are not completed (4) | <ul style="list-style-type: none"> – In plot No.9 and 10, three houses that are planned to build as the plots are owned by father and son. The second floors of these three houses are needed to be carried on. – Plot No. 66, the house construction for the first floor has been finished and the second floor is still needed to be carried on. <p>Photos</p> |  <p>House No. 9</p>  <p>House No. 10</p>  <p>House No. 66</p> |

| 3 | Other Issues | <p data-bbox="568 129 702 161"><u>Description</u></p> <table border="1" data-bbox="568 192 1155 430"> <thead> <tr> <th data-bbox="568 192 753 295" rowspan="2">Condition</th> <th colspan="2" data-bbox="759 192 1155 224">No. of HHs</th> </tr> <tr> <th data-bbox="759 232 938 295">This week condition</th> <th data-bbox="944 232 1155 295">Previous week condition</th> </tr> </thead> <tbody> <tr> <td data-bbox="568 304 753 331">Level 1</td> <td data-bbox="759 304 938 331">87</td> <td data-bbox="944 304 1155 331">87</td> </tr> <tr> <td data-bbox="568 340 753 367">Level 2</td> <td data-bbox="759 340 938 367">2</td> <td data-bbox="944 340 1155 367">2</td> </tr> <tr> <td data-bbox="568 376 753 403">Level 3</td> <td data-bbox="759 376 938 403">2</td> <td data-bbox="944 376 1155 403">2</td> </tr> <tr> <td data-bbox="568 412 753 439">Level 4</td> <td data-bbox="759 412 938 439"></td> <td data-bbox="944 412 1155 439"></td> </tr> </tbody> </table> <p data-bbox="568 465 845 497"><Evaluation Criteria></p> <p data-bbox="568 501 654 533">Level 1</p> <p data-bbox="568 537 1372 591">-No mud and no standing water with their own drainage system in their compound</p> <p data-bbox="568 595 654 627">Level 2</p> <p data-bbox="568 631 1139 663">-No mud and no standing water in their compound</p> <p data-bbox="568 667 660 698">Level 3</p> <p data-bbox="568 703 1228 734">- Some or little mud and standing water in their compound</p> <p data-bbox="568 739 654 770">Level 4</p> <p data-bbox="568 775 1155 806">-A lot of mud and standing water in their compound</p> <p data-bbox="568 851 654 882"><u>Photos</u></p> <div data-bbox="574 945 1002 1258"> <p data-bbox="580 954 708 985">Level 1</p>  <p data-bbox="580 1218 772 1249">House No.31</p> </div> <div data-bbox="1021 945 1449 1258"> <p data-bbox="1027 954 1155 985">Level 2</p>  <p data-bbox="1027 1218 1219 1249">House No.19</p> </div> <div data-bbox="574 1267 1002 1581"> <p data-bbox="580 1276 708 1308">Level 3</p>  <p data-bbox="580 1554 772 1585">House No. 64</p> </div> <div data-bbox="1021 1267 1449 1581"> <p data-bbox="1027 1276 1155 1308">Level 4</p>  <p data-bbox="1027 1554 1219 1585">House No. 84</p> </div> <div data-bbox="574 1617 1002 1930"> <p data-bbox="580 1626 708 1657">Level 3</p>  <p data-bbox="580 1908 772 1939">House No. 75</p> </div> <div data-bbox="1021 1617 1449 1930"> <p data-bbox="1027 1626 1155 1657">Level 4</p>  <p data-bbox="1027 1908 1219 1939">House No. 88</p> </div> | Condition | No. of HHs | | This week condition | Previous week condition | Level 1 | 87 | 87 | Level 2 | 2 | 2 | Level 3 | 2 | 2 | Level 4 | | |
|-----------|---------------------|--|-----------|------------|--|---------------------|-------------------------|---------|----|----|---------|---|---|---------|---|---|---------|--|--|
| Condition | No. of HHs | | | | | | | | | | | | | | | | | | |
| | This week condition | Previous week condition | | | | | | | | | | | | | | | | | |
| Level 1 | 87 | 87 | | | | | | | | | | | | | | | | | |
| Level 2 | 2 | 2 | | | | | | | | | | | | | | | | | |
| Level 3 | 2 | 2 | | | | | | | | | | | | | | | | | |
| Level 4 | | | | | | | | | | | | | | | | | | | |

| <p>(2) Plantation</p> | <p>- In front of the compounds, the shady trees, fruit trees, flowering plants and vegetables are being planted.</p> <p><u>Description</u></p> <p>- In front of the compounds, the shade trees, fruit trees, flowering plants and vegetables are being planted.</p> <table border="1" data-bbox="571 331 1439 943"> <thead> <tr> <th>Type</th> <th>No. of HHs</th> <th>Remarks</th> </tr> </thead> <tbody> <tr> <td>Shade tree</td> <td>15</td> <td>Albizzia, Indian almond, Neem tree, etc. HH No. 20, 40, 43, 48, 51, 57, 59, 61, 62, 67, 69, 72, 73, 77, 85</td> </tr> <tr> <td>Fruit tree</td> <td>37</td> <td>Banana, Mango, sugar cane, coconut, citrus and jack fruit etc. HH No. 3, 15, 17, 20,21, 23, 28, 30, 31, 32, 34, 37, 40, 41, 48, 51, 52, 55, 57, 58, 59, 61, 62, 63, 67, 68, 70, 71, 72, 73, 77, 78, 82, 85, 86, 88</td> </tr> <tr> <td>Vegetables</td> <td>20</td> <td>Chili, tomato, bitter gourd, Roselle, gourd, basils, eggplant etc. HH No. 12, 17, 21, 41, 49, 58, 59, 61, 62, 63, 67, 68, 70, 71, 72, 73, 77, 82, 85, 86</td> </tr> <tr> <td>Flowering plant</td> <td>31</td> <td>Jasmine, poinsettia, orchid, kiss me quick, etc. HH No. 3, 5, 6, 8, 10, 12, 13, 14, 17, 20, 21, 22, 23, 29, 30, 31, 32, 46, 48, 58, 59, 61, 62, 65, 67, 68, 69, 72, 77, 78, 86</td> </tr> </tbody> </table> | Type | No. of HHs | Remarks | Shade tree | 15 | Albizzia, Indian almond, Neem tree, etc. HH No. 20, 40, 43, 48, 51, 57, 59, 61, 62, 67, 69, 72, 73, 77, 85 | Fruit tree | 37 | Banana, Mango, sugar cane, coconut, citrus and jack fruit etc. HH No. 3, 15, 17, 20,21, 23, 28, 30, 31, 32, 34, 37, 40, 41, 48, 51, 52, 55, 57, 58, 59, 61, 62, 63, 67, 68, 70, 71, 72, 73, 77, 78, 82, 85, 86, 88 | Vegetables | 20 | Chili, tomato, bitter gourd, Roselle, gourd, basils, eggplant etc. HH No. 12, 17, 21, 41, 49, 58, 59, 61, 62, 63, 67, 68, 70, 71, 72, 73, 77, 82, 85, 86 | Flowering plant | 31 | Jasmine, poinsettia, orchid, kiss me quick, etc. HH No. 3, 5, 6, 8, 10, 12, 13, 14, 17, 20, 21, 22, 23, 29, 30, 31, 32, 46, 48, 58, 59, 61, 62, 65, 67, 68, 69, 72, 77, 78, 86 |
|-----------------------|---|---|------------|---------|------------|----|---|------------|----|---|------------|----|---|-----------------|----|---|
| Type | No. of HHs | Remarks | | | | | | | | | | | | | | |
| Shade tree | 15 | Albizzia, Indian almond, Neem tree, etc. HH No. 20, 40, 43, 48, 51, 57, 59, 61, 62, 67, 69, 72, 73, 77, 85 | | | | | | | | | | | | | | |
| Fruit tree | 37 | Banana, Mango, sugar cane, coconut, citrus and jack fruit etc. HH No. 3, 15, 17, 20,21, 23, 28, 30, 31, 32, 34, 37, 40, 41, 48, 51, 52, 55, 57, 58, 59, 61, 62, 63, 67, 68, 70, 71, 72, 73, 77, 78, 82, 85, 86, 88 | | | | | | | | | | | | | | |
| Vegetables | 20 | Chili, tomato, bitter gourd, Roselle, gourd, basils, eggplant etc. HH No. 12, 17, 21, 41, 49, 58, 59, 61, 62, 63, 67, 68, 70, 71, 72, 73, 77, 82, 85, 86 | | | | | | | | | | | | | | |
| Flowering plant | 31 | Jasmine, poinsettia, orchid, kiss me quick, etc. HH No. 3, 5, 6, 8, 10, 12, 13, 14, 17, 20, 21, 22, 23, 29, 30, 31, 32, 46, 48, 58, 59, 61, 62, 65, 67, 68, 69, 72, 77, 78, 86 | | | | | | | | | | | | | | |
| | <p>Photos,</p> <div style="display: flex; flex-wrap: wrap;">     </div> | | | | | | | | | | | | | | | |
| <p>(3) Livestock</p> | <p><u>Description</u></p> <p>-The chicken and geoses are being raised.</p> <table border="1" data-bbox="571 1794 1193 1928"> <thead> <tr> <th>Type</th> <th>No. of HHs</th> <th>Remarks</th> </tr> </thead> <tbody> <tr> <td>Chicken</td> <td>6</td> <td>HH No. 13, 14, 21, 59, 67, 78</td> </tr> <tr> <td>Goose</td> <td>2</td> <td>HH No. 40, 67</td> </tr> </tbody> </table> | Type | No. of HHs | Remarks | Chicken | 6 | HH No. 13, 14, 21, 59, 67, 78 | Goose | 2 | HH No. 40, 67 | | | | | | |
| Type | No. of HHs | Remarks | | | | | | | | | | | | | | |
| Chicken | 6 | HH No. 13, 14, 21, 59, 67, 78 | | | | | | | | | | | | | | |
| Goose | 2 | HH No. 40, 67 | | | | | | | | | | | | | | |

Photos

