





Surveyor: Zaw La

Date Visited: 8.10.2015





Time Visited: 11:10 to 12:20

Weather Condition: Sunny

The last time of heavy raining: - Yesterday

| No | Item | Condition | Description and Photos |
|----|-----------------------|---|--|
| 1 | Condition of - | | |
| | (1). Well | Improved <input type="checkbox"/> Same <input checked="" type="checkbox"/> * Worse <input type="checkbox"/> <i>*as last week</i> | Description & Photos: -See ANNEX.1 - Although both of the two open wells are dirty, it seems that muddy water under the ground is passing through the crack at the wall of the well. Compared with last week, well no. 1 is gradually clean this week and used by surrounding people again. In terms of avoiding the muddy groundwater passing to the well, both open wells need to be renovated again in summer. The buffers of some hand pumps need to be changed, but people get water from their own well or rain water currently. |
| | (2). Drainage | Improved <input type="checkbox"/> Same <input checked="" type="checkbox"/> * Worse <input type="checkbox"/> <i>*as last week</i> | Description -Water level in the drainage canals are increased than last week because there was heavy rain yesterday. The stream along the drainage canal may need to be rehabilitated in order to improve the water-flow in coming summer period. Photos <div style="display: flex; flex-wrap: wrap;"> <div style="width: 50%; text-align: center;">  <p>Near Well No. 1</p> </div> <div style="width: 50%; text-align: center;">  <p>Near HH No. 48</p> </div> <div style="width: 50%; text-align: center;">  <p>Near HH No. 1</p> </div> <div style="width: 50%; text-align: center;">  <p>Near garbage pit</p> </div> </div> |



| | | |
|------------------|---|---|
| <p>(3). Road</p> | <p>Improved <input type="checkbox"/> Same <input checked="" type="checkbox"/>* Worse <input type="checkbox"/> <i>*as last week</i></p> | <p><u>Description</u> -The roads, except some places have muddy, are almost being dry and no problem for walking.</p> <p><u>Photos</u></p> <div style="display: flex; flex-wrap: wrap;"> <div style="width: 50%; text-align: center;"> <p>Front main road</p>  </div> <div style="width: 50%; text-align: center;"> <p>The right road of relocation site</p>  </div> <div style="width: 50%; text-align: center;"> <p>Middle road</p>  </div> <div style="width: 50%; text-align: center;"> <p>The left road of relocation site</p>  </div> </div> |
|------------------|---|---|

| | | |
|---------------------------------------|---|--|
| <p>(4). Garbage Condition</p> | <p>Improved <input type="checkbox"/> Same <input checked="" type="checkbox"/>* Worse <input type="checkbox"/></p> | <p><u>Description</u> -Garbage pit is being used by people. -Garbage pit was gradually increased with trash about half-full again and it needs to be collected again. -People throw garbage at the backside of Third Row and it needs to be clean up too.</p> |
|---------------------------------------|---|--|



N
o
1

Item
(5). Fly proof toilet

Condition
Improved *
Same
Worse
**as last week*

Description

-All of fly proof toilets are used by people.
-Almost all of fly proof toilets made by wood or bamboo have been lifted up as shown in below pictures and are convenient to use. Some concrete toilets are still needed to be renovated too as their floors are low and will be inconvenient to use sometimes when there is heavy rain and groundwater level is raised.

| Condition | No. of HHs | |
|-----------|---------------------|-------------------------|
| | This week condition | Previous week condition |
| Level 1 | 50 | 50 |
| Level 2 | 16 | 16 |
| Level 3 | 0 | 0 |
| Level 4 | 0 | 0 |
| No Toilet | 2 | 2 |

<Evaluation Criteria>

Level 1

- Fly proof toilet is not needed to be repaired.
- No/rarely toilet unavailable

Level 2



- Fly proof toilet is needed to be repaired.
- Rarely toilet unavailable



Level 3

- Fly proof toilet is needed to be repaired.
- Often toilet unavailable
- As the result of filling the soil and also raining, some toilets are inconvenience to use.


Level 4

- Fly proof toilet is urgently needed to be repaired.
- Often toilet unavailable
- After filling the soil, some toilets need to be lifted up.

| | | | | |
|--|--|--|---|--|
| | | | <p>Level 1 HH No. 6</p>  | <p>Level 2 HH No. 12</p>  |
| | | | <p>Level 3 HH No. 31</p>  | <p>Level 4 HH No. 35</p>  |

| | | | |
|---------------------|---|---|--|
| (6). Electricity | <p>Improved <input type="checkbox"/></p> <p>Same <input checked="" type="checkbox"/>*</p> <p>Worse <input type="checkbox"/></p> <p><i>*as last week</i></p> | <p><u>Description</u></p> <ul style="list-style-type: none"> -Electricity comes regularly. -Electric poles and transformer are being supported with a good foundation. -But, there is a hole at an electric pole which was hit by a truck car. The electric pole needs to be renovated. <p><u>Photos</u></p> | <p>In front of HH No. 24</p>   |
|---------------------|---|---|--|



| No | Item | Condition | Description and Photos |
|----|---|--|---|
| 2 | House Construction | No. of houses not completed (2) | <p><u>Description</u> -HH No.5, the construction for kitchen, toilet and water tank seems to be stopped again.</p>  |
| 3 | Living Status of PAPs (Sold house, renting, etc.) | <p><u>Description</u></p> <p>(1) House ownership (1)-1 No. of house that are owned by PAPs (50) (1)-2 No. of house that were sold (18)</p> <p>(2) Living condition (2)-1 No. of houses where PAPs live (41) (2)-2 No. of houses where original PAPs lives do not live (22) (2)-3 No. of houses where nobody lives (5)</p> | Location Map: See ANNEX.2 |

| 4 | Other issue | | | | | | | | | | | | | | | | | | | |
|-----------|---|--|-----------|------------|--|---------------------|-------------------------|---------|----|----|---------|----|----|---------|---|----|---------|---|---|--|
| | (1). Drainage condition for rain water in their compounds | <p><u>Description</u> -Rainy season has started. -Some of the compounds are wet.</p> <table border="1"> <thead> <tr> <th rowspan="2">Condition</th> <th colspan="2">No. of HHs</th> </tr> <tr> <th>This week condition</th> <th>Previous week condition</th> </tr> </thead> <tbody> <tr> <td>Level 1</td> <td>35</td> <td>35</td> </tr> <tr> <td>Level 2</td> <td>28</td> <td>21</td> </tr> <tr> <td>Level 3</td> <td>5</td> <td>10</td> </tr> <tr> <td>Level 4</td> <td>0</td> <td>2</td> </tr> </tbody> </table> <p><Evaluation Criteria> Level 1 -No mud and no standing water with their own drainage system in their compound</p> | Condition | No. of HHs | | This week condition | Previous week condition | Level 1 | 35 | 35 | Level 2 | 28 | 21 | Level 3 | 5 | 10 | Level 4 | 0 | 2 | |
| Condition | No. of HHs | | | | | | | | | | | | | | | | | | | |
| | This week condition | Previous week condition | | | | | | | | | | | | | | | | | | |
| Level 1 | 35 | 35 | | | | | | | | | | | | | | | | | | |
| Level 2 | 28 | 21 | | | | | | | | | | | | | | | | | | |
| Level 3 | 5 | 10 | | | | | | | | | | | | | | | | | | |
| Level 4 | 0 | 2 | | | | | | | | | | | | | | | | | | |

Level 2

-No mud and no standing water in their compound

Level 3

- Some or little mud and standing water in their compound

Level 4

-A lot of mud and standing water in their compound

Photos



4 (2) Plantation

Description

-In front of their compounds, the people planted shady trees, fruit trees, vegetables and floral plants.

| Type | No. of HHs | Remarks |
|--------------|------------|--|
| Shady tree | 21 | Albizia, Indian almond, etc. HH No. 2, 3, 14, 15,16, 17, 18, 19, 20, 23, 25, 26, 27, 32, 33, 39, 41, 44, 48, 58 and 65 |
| Fruit tree | 27 | Banana, Mango, sugarcane, coconut, citrus, etc. HH No.1, 2, 3, 4, 8, 9, 11, 17, 24, 25, 27, 29, 30, 34, 36, 37, 38, 39, 40, 41, 43, 45, 46, 47, 48, 65 and 67 |
| Vegetable | 11 | Spices, peas, roselle, etc. HH No. 15, 23, 25, 38, 39, 40, 42,45, 58, 63 and 67 |
| Floral plant | 26 | Many species. HH No. 2, 9, 14, 15, 17, 18, 19, 21, 26, 27, 30, 31, 32, 33, 38, 39, 40, 41, 42, 43, 47, 48, 58, 59, 62 and 65 |



4 (3) Livestock

Description

-The people are raising chicken, ducks, goats, pigs and cows.
 -Even though they have cows, some houses do not keep their cows in relocation site instead they keep in their farms or other places.

| Type | No. of HHs | Remarks |
|-------------------|------------|---|
| Cow | 4 | HH No. 1, 42, 47 and 54 |
| Pig | - | - |
| Goat | 3 | HH No.15, 47, 50 |
| Chicken and ducks | 18 | HH No. 3, 4, 8, 12, 14, 15, 20, 28, 30, 32, 41, 47, 50, 51, 52, 54, 56 and 62 |

Photos



ANNEX.1

As of 8.10.2015

Water is clean and people nearby are using it for drinking and living use . A pulley wheel, bucket and a rope have been set up but the rope seems to be thin and it is better to be changed with thick one for the better use.



Hand pump isn't functioned.

This hand pump is functioned very well. Water is clean and people nearby are using this hand pump for drinking and living use.

As the buffer has been changed with the new one and the hand pump is functioned very well now. Water is also clean and people living nearby use it for drinking and living use again.

This well cannot be used as water is dirty. A pulley wheel, bucket and a rope have been set up but the rope seems to be thin and it is better to be changed with a thick one for the better use.



The buffer of the hand pump needs to be change. Therefore, people living nearby are using water from their owned pump or rain water at the moment.



This hand pump is functioned very well. Water is clean and people living nearby are using this hand pump. Moreover water filter tank for remove the smell of iron has been set up beside the hand pump. There is no smell of iron and people enjoy water for drinking and living use.



- Closed Well
- New Well (Hand pump)
- Open Well
- Hand Pump
- Private Well

