

WeeklyFieldReport

No.32

SurveyorZawLa

DateVisited:10.6.2015

TimeVisited:15:00to16:30

WeatherCondition:Sunny

The last time of heavy raining: . r

No	Item	Condition	DescriptionandPhotos
1	Conditionof r		
	(1). Well	Improved ~ Same Worse ´ *as last week	Description & Photos: See ANNEX.1 Two wells and all hand pumps except near transformer are well functioned, water is clean and water amount is enough to use as the raining season is nearer and underground water level is raising up. Therefore no problem for clean water.
	(2). Drainage	Improved ´ Same ~ Worse ´ *as last week	Description Water level in the drainage canal is increased a lot than last week because there was a heavy rain about two days ago. Though the drainage canal has increased with water the resident places are not much problem because the soil filling in each compound has done. Photos

	(3).Road	Improved Same ~ Worse *aslastweek	<u>Description</u> Theroadsareabitwetandtherearesomemuddyintheroadsbut noproblemforwalkingsofar.Asmentionedinthepictures,theroads haven'tcleanupyetafterfillingthesoiltoresidentsots.
			<u>Photos</u>
	(4).Garbage Condition	Improved Same ~ Worse	<u>Description</u> Garbagepitisusedbypeople. Garbagepitisoverfullanditneedstobecleanedup. Therearesomesmellsfromgarbagepit. PeoplethrowgarbageatthebacksideofThirdRow. <div style="display: flex; justify-content: space-around; margin-top: 20px;"> <div data-bbox="634 1241 789 1287" style="border: 1px solid black; padding: 2px;">Garbage Pit</div> <div data-bbox="1024 1241 1260 1287" style="border: 1px solid black; padding: 2px;">Garbage Pit</div> </div> <div style="display: flex; justify-content: space-around; margin-top: 20px;"> <div data-bbox="630 1549 865 1596" style="border: 1px solid black; padding: 2px;">Garbage Pit</div> <div data-bbox="1019 1549 1377 1596" style="border: 1px solid black; padding: 2px;">GarbageatthebacksideofThirdRow</div> </div>

			Near transformer	Drainage canal near HH No. 48																				
No	Item	Condition	Description and Photos																					
1	(5). Flyproof toilet	Improved Same ~ Worse *as last week	<p><u>Description</u> All of flyproof toilets are used by people.</p> <table border="1"> <thead> <tr> <th rowspan="2">Condition</th> <th colspan="2">No. of HHs</th> </tr> <tr> <th>This week condition</th> <th>Previous week condition</th> </tr> </thead> <tbody> <tr> <td>Level1</td> <td>20</td> <td>42</td> </tr> <tr> <td>Level2</td> <td>10</td> <td>21</td> </tr> <tr> <td>Level3</td> <td>28</td> <td>0</td> </tr> <tr> <td>Level4</td> <td>5</td> <td>0</td> </tr> <tr> <td>No Toilet</td> <td>5</td> <td>5</td> </tr> </tbody> </table> <p>&lt;Evaluation Criteria&gt;  <b>Level 1</b>            No need to repair flyproof toilet            No/rarely toilet unavailable  <b>Level 2</b>            Need to repair flyproof toilet            Rarely toilet unavailable  <b>Level 3</b>            Need to repair flyproof toilet            Oftent toilet unavailable            As the result of filling the soil and also raining, some toilets are inconvenient to use.  <b>Level 4</b>            Need to repair urgently flyproof toilet            Oftent toilet unavailable            After filling the soil, some toilets need to be lifted up.</p>	Condition	No. of HHs		This week condition	Previous week condition	Level1	20	42	Level2	10	21	Level3	28	0	Level4	5	0	No Toilet	5	5	<p><u>Photos</u></p> <p>HH No. 55</p> <p>Level1</p> <p>HH No. 31</p> <p>Level2</p> <p>HH No. 12</p> <p>Level1</p>
Condition	No. of HHs																							
	This week condition	Previous week condition																						
Level1	20	42																						
Level2	10	21																						
Level3	28	0																						
Level4	5	0																						
No Toilet	5	5																						
	(6). Electricity	Improved Same ~ Worse	<p><u>Description</u> Electricity comes regularly. Electric poles and transformers are supported with good foundation.</p>																					

		*aslastweek	<u>Photos</u>
--	--	-------------	---------------

No	Item	Condition	Description and Photos
2	House Construction	No. of houses not completed (2)	<p><u>Description</u></p> <p>HHNo.1 is almost renovated except fencing the compound and it will suppose to be finished with in next week by the house owner as he would like to do himself.</p> <p>HHNo.5, the construction for kitchen, toilet and water tank seem to be started again.</p> <p>Soil filling work has almost done for all the compounds of the PAP's, but some houses like HH no. 1 need to be reduced the soil because they have overfilled already.</p> <p><u>Photos</u></p> <div style="display: flex; justify-content: space-around; align-items: center;"> <div style="border: 1px solid black; padding: 5px; margin: 5px;">HHNo. 1</div> <div style="border: 1px solid black; padding: 5px; margin: 5px;">HHNo. 5</div> </div>
3	Living Status of PAPs (Sold house, renting etc.)	<p><u>Description</u></p> <p>(1) House ownership</p> <p>(1) 1 No. of houses that are owned by PAPs (48)</p> <p>(1) 2 No. of houses that were sold (20)</p> <p>(2) Living condition</p> <p>(2) 1 No. of houses where PAPs live (38)</p> <p>(2) 2 No. of houses where not original PAPs live (22)</p> <p>(2) 3 No. of houses where nobody lives (8)</p>	

		Location Map: See ANNEX.2																	
4	Other issues																		
	(1). Drainage condition for rainwater in their compounds	<p><u>Description</u>  Rainy season is going to start.  Most of the compound area bit wet.</p> <table border="1"> <thead> <tr> <th rowspan="2">Condition</th> <th colspan="2">No. of HHs</th> </tr> <tr> <th>This week condition</th> <th>Previous week condition</th> </tr> </thead> <tbody> <tr> <td>Level 1</td> <td>14</td> <td>14</td> </tr> <tr> <td>Level 2</td> <td>30</td> <td>30</td> </tr> <tr> <td>Level 3</td> <td>20</td> <td>20</td> </tr> <tr> <td>Level 4</td> <td>4</td> <td>4</td> </tr> </tbody> </table> <p>&lt;Evaluation Criteria&gt;  <b>Level 1</b>  No mud and no standing water with their own drainage system in their compound  <b>Level 2</b>  No mud and no standing water in their compound  <b>Level 3</b>  Some or little mud and standing water in their compound  <b>Level 4</b>  A lot of mud and standing water in their compound</p> <p>The soil filling work has just finished and therefore it is still soft and need to wait time for hard.</p>	Condition	No. of HHs		This week condition	Previous week condition	Level 1	14	14	Level 2	30	30	Level 3	20	20	Level 4	4	4
Condition	No. of HHs																		
	This week condition	Previous week condition																	
Level 1	14	14																	
Level 2	30	30																	
Level 3	20	20																	
Level 4	4	4																	
4	(2) Plantation	<p><u>Description</u>  In front of their compounds, they planted shady trees, fruit trees, vegetable and floral plants.</p>																	

Type	No. of HHs	Remarks																		
Shadytree	12	Albizzia,Indianalmond,etc. HHNo. 2, 3, 14, 19, 20, 21, 25, 27, 29, 32, 41 and 65																		
Fruittree	24	BananaMango,sugarcane,coconut,citrusetc. HHNo. 2, 3, 4, 7, 8, 9, 11, 17, 21, 24, 25, 27, 33, 37, 38, 39, 41, 43, 45, 46, 47, 48, 54 and 65																		
Vegetable	10	Spicespeas,roselleetc. HHNo. 22, 23, 25, 27, 38, 39, 40, 42, 45 and 63																		
Floralplant	20	Manyspecies. HHNo. 2, 9, 14, 15, 17, 21, 23, 27, 32, 33, 38, 39, 40, 41, 42, 43, 47, 48, 58 and 65																		
<u>Photos</u>																				
4	(3)Livestock	<p><u>Description</u> Theyareraisingchickenducksgoatspigsandcows. Eventhoughtheyhavecowstheydonotkeeptheircowsinrelocationiteinstead theykeepin theirfarmsorotherplaces.</p> <table border="1"> <thead> <tr> <th>Type</th> <th>No. of HHs</th> <th>Remarks</th> </tr> </thead> <tbody> <tr> <td>Cow</td> <td>5</td> <td>HHNo. 3, 18, 42, 47 and 54</td> </tr> <tr> <td>Pig</td> <td></td> <td></td> </tr> <tr> <td>Goat</td> <td>1</td> <td>HH.47</td> </tr> <tr> <td>Chickerand ducks</td> <td>15</td> <td>HHNo. 4, 8, 12, 14, 28, 30, 32, 41, 47, 50, 51, 52, 55, 56 and 62</td> </tr> <tr> <td></td> <td></td> <td></td> </tr> </tbody> </table>	Type	No. of HHs	Remarks	Cow	5	HHNo. 3, 18, 42, 47 and 54	Pig			Goat	1	HH.47	Chickerand ducks	15	HHNo. 4, 8, 12, 14, 28, 30, 32, 41, 47, 50, 51, 52, 55, 56 and 62			
Type	No. of HHs	Remarks																		
Cow	5	HHNo. 3, 18, 42, 47 and 54																		
Pig																				
Goat	1	HH.47																		
Chickerand ducks	15	HHNo. 4, 8, 12, 14, 28, 30, 32, 41, 47, 50, 51, 52, 55, 56 and 62																		

		<u>Photos</u>
5	Remarks	For avoiding from flood, each of the PAPs compounds have been fenced by retaining wall, the stands of the houses are painted by water proofing paint or making concrete protection. Moreover each of the PAPs compounds had done filling with the soil.

# ANNEX.1

As of 1.6.2015

