

Weekly Field Report

No. 14


Surveyor: Sithu Nyein








Date Visited: 25.11.2014








Time Visited: 10:30 to 12:00


Weather Condition: Sunny


The last time of heavy raining: -

No	Item	Condition	Description and Photos
1	Condition of -		
	(1). Well	Improved <input type="checkbox"/> Same <input checked="" type="checkbox"/> Worse <input type="checkbox"/>	Description & Photos: -See ANNEX.1 -Hand Pump of Well No. 6, 9, and 11 are needed to repair.
	(2). Drainage	Improved <input checked="" type="checkbox"/> Same <input type="checkbox"/> Worse <input type="checkbox"/>	<p><u>Description</u></p> <p>-Water level in the drainage canal is near to the bottom. -Drainage canals are functioned properly.</p> <p><u>Photos</u></p> 
	(3). Road	Improved <input type="checkbox"/> Same <input checked="" type="checkbox"/> * Worse <input type="checkbox"/> <i>*as last week</i>	<p><u>Description</u></p> <p>-The roads are almost dry and no problem for traffic as a whole.</p>

			<p><u>Photos</u></p> 
	<p>(4). Garbage Condition</p>	<p>Improved <input type="checkbox"/>          Same <input checked="" type="checkbox"/>          Worse <input type="checkbox"/></p>	<p><u>Description</u></p> <ul style="list-style-type: none"> <li>-Garbage pit is used by people.</li> <li>-Garbage pit is almost half-full.</li> <li>-There is no strong smell.</li> </ul> <div style="display: flex; flex-wrap: wrap;"> <div style="width: 50%; text-align: center;">  <p>Garbage Pit</p> </div> <div style="width: 50%; text-align: center;">  <p>Garbage Pit</p> </div> <div style="width: 50%; text-align: center;">  <p>Garbage Pit</p> </div> <div style="width: 50%; text-align: center;">  <p>Garbage at the backside of HH No.49</p> </div> <div style="width: 50%; text-align: center;">  <p>Near transformer</p> </div> <div style="width: 50%; text-align: center;">  <p>Drainage canal near HH No.48</p> </div> </div>

No	Item	Condition	Description and Photos																					
1	(5). Fly proof toilet	Improved <input type="checkbox"/> Same <input checked="" type="checkbox"/> Worse <input type="checkbox"/> <i>*as last week</i>	<u>Description</u> -All of fly proof toilets are being used by people.	<u>Photos</u>   																				
			<table border="1"> <thead> <tr> <th rowspan="2">Condition</th> <th colspan="2">No. of HHs</th> </tr> <tr> <th>This week condition</th> <th>Previous week condition</th> </tr> </thead> <tbody> <tr> <td>Level 1</td> <td>42</td> <td>42</td> </tr> <tr> <td>Level 2</td> <td>21</td> <td>21</td> </tr> <tr> <td>Level 3</td> <td>0</td> <td>0</td> </tr> <tr> <td>Level 4</td> <td>0</td> <td>0</td> </tr> <tr> <td>No Toilet</td> <td>5</td> <td>5</td> </tr> </tbody> </table> <u>&lt;Evaluation Criteria&gt;</u> <b>Level 1</b> -No need to repair fly proof toilet -No/rarely toilet unavailable <b>Level 2</b> -Need to repair fly proof toilet -Rarely toilet unavailable <b>Level 3</b> -Need to repair fly proof toilet -Often toilet unavailable <b>Level 4</b> -Need to repair urgently fly proof toilet -Often toilet unavailable	Condition	No. of HHs		This week condition	Previous week condition	Level 1	42	42	Level 2	21	21	Level 3	0	0	Level 4	0	0	No Toilet	5	5	
Condition	No. of HHs																							
	This week condition	Previous week condition																						
Level 1	42	42																						
Level 2	21	21																						
Level 3	0	0																						
Level 4	0	0																						
No Toilet	5	5																						
	(6). Electricity	Improved <input type="checkbox"/> Same <input checked="" type="checkbox"/> * Worse <input type="checkbox"/> <i>*as last week</i>	<u>Description</u> -Electricity is coming regularly -Electric poles and transformer are supported in good foundation.	<u>Photos</u>    																				

No	Item	Condition	Description and Photos																	
2	House Construction	No. of houses not completed (2)	<p><u>Description</u>            -HH No.1 doesn't have ladder and nobody is living            -In HH No.5, the construction for kitchen, toilet and water tank seems stopped. Nobody lives.</p> <p><u>Photos</u></p> 																	
3	Living Status of PAPs (Sold house, renting, etc.)	<p><u>Description</u>            (1) House ownership                (1)-1 No. of house that are owned by PAPs (49)                (1)-2 No. of house that were sold (19)            (2) Living condition                (2)-1 No. of houses where PAPs live (39)                (2)-2 No. of houses where not original PAPs lives (24)                (2)-3 No. of houses where nobody lives (5)            Yellow= Changes from previous week</p>	<p>Location Map: See ANNEX.2</p>																	
4	Other issues		<p>(1). Drainage condition for rain water in their compounds</p> <p><u>Description</u>            -There are puddles and muddy areas in some compounds.            -But most of the compounds are almost dry.</p> <table border="1" data-bbox="400 1323 987 1563"> <thead> <tr> <th rowspan="2">Condition</th> <th colspan="2">No. of HHs</th> </tr> <tr> <th>This week condition</th> <th>Previous week condition</th> </tr> </thead> <tbody> <tr> <td>Level 1</td> <td>15</td> <td>15</td> </tr> <tr> <td>Level 2</td> <td>38</td> <td>36</td> </tr> <tr> <td>Level 3</td> <td>15</td> <td>16</td> </tr> <tr> <td>Level 4</td> <td>0</td> <td>1</td> </tr> </tbody> </table> <p><b>&lt;Evaluation Criteria&gt;</b>  <b>Level 1</b>            -No mud and no standing water with their own drainage system in their compound  <b>Level 2</b>            -No mud and no standing water in their compound  <b>Level 3</b>            - Some or little mud and standing water in their compound  <b>Level 4</b>            -A lot of mud and standing water in their compound</p>	Condition	No. of HHs		This week condition	Previous week condition	Level 1	15	15	Level 2	38	36	Level 3	15	16	Level 4	0	1
Condition	No. of HHs																			
	This week condition	Previous week condition																		
Level 1	15	15																		
Level 2	38	36																		
Level 3	15	16																		
Level 4	0	1																		



4 (2)  
Plantation

Description

-In front of their compounds, they planted shady trees, fruit trees, vegetables and floral plants.

Type	No. of HHs	Remarks
Shady tree	12	Albizzia, Indian almond, etc. HH No. 2, 3, 14, 19, 20, 21, 25, 27, 29, 32, 41 and 65
Fruit tree	24	Banana, Mango, sugarcane, coconut, citrus, etc. HH No. 2, 3, 4, 7, 8, 9, 11, 17, 21,24, 25, 27, 33, 37, 38, 39, 41, 43, 45, 46, 47, 48, 54 and 65
Vegetable	10	Spices, peas, roselle, etc. HH No. 22, 23, 25, 27, 38, 39, 40, 42,45 and 63
Floral plant	20	Many species. HH No. 2, 9, 14, 15, 17,21, 23, 27, 32, 33, 38, 39, 40, 41, 42, 43, 47, 48, 58 and 65

Photos





4 (3) Livestock

Description

-They are raising chicken, ducks, goats, pigs and cows.  
 -Even though they have cows, they do not keep their cows in relocation site instead they keep in their farms or other places.

Type	No. of HHs	Remarks
Cow	5	HH No. 3, 18, 42, 47 and 54
Pig	1	HH No. 2
Goat	2	HH No. 50 and 51
Chicken and ducks	15	HH No. 4, 8, 12, 14, 28, 30, 32, 41, 47, 50, 51, 52, 55, 56 and 62

dPhotos



5 **Remarks**


-In HH No.10, nobody lives now. Previously, people who do the sewing business rented this house.



Water is clean and has no sand, no clay and no smell. People are using this well for cooking and washing. Sometimes they are drinking



The color of water likes gray and has no sand, no clay and no smell. People are not using this well. Because nearby well No. 2 and 10 are used.



Hand pump is functioned. Water is clean and has no sand, no clay but it has smell of mud. People are using this well for washing. Some people who live nearby buy water from private well of HH No.43 for washing, cooking and drinking. They have to pay 100 Ks per day of use. They take water to their houses with movable pipe.



Hand pump isn't functioned very well. The washer needs to be repaired. People are using this well for cooking and washing. Sometimes they are drinking.



Hand pump isn't functioned.



Hand pump isn't functioned very well. The washer needs to be repaired. People who live nearby aren't using this well. People buy water from private well of HH No.4 for washing, cooking and drinking. They have to pay 100 Ks per day of use. They take water to their houses with movable pipe.



-  **Closed Well**
-  **New Well (Hand pump)**
-  **Open Well**
-  **Hand Pump**
-  **Private Well**

Hand pump is functioned. Water is clean and has no sand, no clay, and no smell. People are using this well for cooking and washing. Sometimes they are drinking.

