Weekly Field Report

Surveyor: Sithu Nyein
Date Visited: 02.9.2014
Time Visited: 14:00 to 16:00

Weather Condition: Partly Cloudy

The last time of heavy raining: 5 days ago

No	Item	Condition	Description and Photos		
1	Condition of -				
	(1). Well	Improved □ Same *Worse □ *as last week	Description & Photos: -See ANNEX.1 -Hand Pumps of Well No.6 and No.9 are needed to repair. Description Water level in the drainage canal is near to the bottom. Photos Photos		
	(2). Drainage	Improved □ Same ©			
		Worse □ *as last week			

No	Item	Condition	Description and Photos	
1	(3). Road	Improved □ Same * ** ** ** ** ** ** ** ** *	<u>Description</u> -There are some puddles and partly muddy areas but the roads are almost dry and no problem for traffic as a whole.	
		Worse □ *as last week	Photos Image: Photos Image: Photos	

No	Item	Condition	Description and Photos		
1	(4). Garbage Condition	Improved □ Same * Worse □ *as last week	Description -Water level near garbage pit becomes lowerGarbage pit is used by some peopleSmells are emerging from garbage pitEspecially people who live in third row throw away the garbage in the backside of their compounds over the fenceSome people put the garbage near electrical transformerGarbage is thrown away in the drainage canal.		
			Garbage Pit Garbage Pit		
			Garbage Pit Garbage at the backside of HH No.49		
			Near transformer Drainage canal near HH No.48		

No	Item	Condition	Description and Photos
1	(5). Fly proof	Improved □	<u>Description</u> <u>Photos</u>
	toilet	Same	-All of fly proof toilets are being
			used by people. HH No. 12
		Worse □	
		*as last week	No. of HHs
			Condition This week week Previous
			condition condition
			Level 1 42 42
			Level 2 21 21 Level 1
			Level 3 0 0 HH No. 31
			Level 4 0 0 HH NO. 31
			No Toilet 5 5
			Evaluation Criteria> Level 1 -No need to repair fly proof toilet -No/rarely toilet unavailable Level 2 -Need to repair fly proof toilet -Rarely toilet unavailable Level 3 -Need to repair fly proof toilet HH No. 55
	(6).	Improved □	-Often toilet unavailable Level 4 -Need to repair urgently fly proof toilet -Often toilet unavailable Description
	Electricity	Same © * Worse □	-Electricity is coming regularlyElectric poles and transformer are supported in good foundation.
		*as last week	Photos A control of the control of

No	Item	Condition	Description and Photos			
2	House Construction	No. of houses not completed (2)	Description -HH No.1 doesn't have ladder and nobody is livingIn HH No.5, the construction for kitchen, toilet and water tank seems stopped. Nobody livesIn HH No.5, sun shade of this house is collapsed due to wind. Wind is not so strong but the quality of the sun shade is not so good enough. Photos HH No. 1 HH No. 5 HH No. 5			
3	Living Status of PAPs (Sold house, renting, etc.)	(1)-2 N (2) Living condi (2)-1 N (2)-2 N (2)-3 N Yellow = cha -HH No.57 is re	ownership -1 No. of house that are owned by PAPs (49) -2 No. of house that were sold (19)			

No	Item	Description and Photos				
4	Other issues					
	(1). Drainage	Description				
	condition for	-In this week, there is no heavy rain.				
	rain water in	-But there are some puddles and muddy areas in most of the compounds.				
	their		·	•	·	
	compounds	No. of HHs				
		Condition	This week	Previous week		
			condition	condition	_	
		Level 1	6	6	_	
		Level 2	24	28		
		Level 3	23	23		
		Level 4	15	11		
		<evaluation criteria=""></evaluation>				
		Level 1				
			standing water w	ith their own drair	age system in their compound	
		Level 2	standing water in	their compound		
		-No mud and no standing water in their compound Level 3				
		Level 3 - Some or little mud and standing water in their compound				
		- Some or little mud and standing water in their compound Level 4				
		-A lot of mud and standing water in their compound				
		<u> </u>				
		HH No. 47 HH No. 14				
		HH No. 14				
		Level 2				
		HH No. 52 HH No. 11				
		The state of the s				
				16		
		Level 3		P	Level 4	
			A CONTRACTOR OF THE PARTY OF TH	THE PARTY OF THE P	The second secon	

No	Item	Description and Photos				
4	(2)	Description		,		
	Plantation	-In front of their compounds, they planted shady plants, fruit trees, vegetables and floral plants				
		Туре	Remarks			
Shady tree 10 Albizzia, Indian almond, etc.				Albizzia, Indian almond, etc. HH No.2, 3, 14, 20, 21, 25, 27, 32, 41, and 65		
		Fruit tree	21 Banana, Mango, sugarcane, coconut, citrus HH No. 2, 3, 4, 7, 8, 9, 11, 17, 21, 25, 33, 37 39, 41, 43, 45, 46, 47, 48 and 65			
		Vegetable	10	Spices, peas, roselle, etc. HH No. 22, 23, 25, 27, 38, 39, 40, 42, 45 and 63		
		Floral plant	18	Many species HH No. 2, 9, 14, 15, 17, 23, 32, 33, 38, 39, 40, 41, 42, 43, 47, 48, 58 and 65		
		Photos		HH No. 17 HH No. 9 HH No. 65		

No	Item	Description and Photos					
4	(3) Livestock	Description					
		-They are raising chicken, ducks, goats, pigs and cows.					
		-Even though they have cows, they do not keep their cows in relocation site instead					
		they keep in their farms or other places.					
		Туре	No. of HHs Remarks				
		Cow	5	HH No. 3, 18, 42, 47			
				and 54			
		Pig	1	HH No. 2			
		Goat	1	HH No. 50			
		Chicken and	9	HH No. 48, 12, 28, 30,			
		ducks		32, 41, 50 and 52			
		<u>Photos</u>					

5 Remarks

- -U Gan Barlu (HH No.3) happened a motor bike accident on Sept 2, 2014 and got minor injuries in his knees. And one of his cows died last week. This cow have an infant cow.
- -U Myint Thu (HH No.43) got injury in his thump on last week. The circle saw run by motor that is used for cutting woods made some cut in his thump. Not serious but he need to see a doctor every day.
- -U Zaw Latt and another man from Mekong Watch came to relocation site on September 2, 2014 according to U Myint Thu said. But their objective isn't known.

ANNEX.1 Updated 02.9.2014

