


Surveyor: Sithu Nyein



Date Visited: 18.2.2014








Time Visited: 10:30 to 02:00


Weather Conditions: Sunny

The last time of heavy raining: four days ago


No	Item	Condition	Description and Photos
1	Condition of - (1). Well	Improved ✓ Same ~ Worse ✓	Description & Photos: -See ANNEX.1 -Hand Pump of Well No., 6, 10, and 11 are needed to repair.
	(2). Drainage	Improved ~ Same ✓ Worse ✓	<p>Description</p> <p>-Water level in the drainage canal is near to the bottom.</p> <p>Photos</p> 
	(3). Road	Improved ✓ Same ~* Worse ✓	<p>Description</p> <p>-The roads are almost dry and no problem for traffic as a whole.</p>

			<p>Photos</p> 
(4). Garbage Condition	Improved Same Worse	<p>Description</p> <ul style="list-style-type: none"> <li>-Garbage pit is used by people</li> <li>-Garbage pit is almost full</li> <li>-There is no strong smell.</li> </ul>	

No	Item	Condition	Description and Photos																					
1	(5).Fly proof toilet	Improved Same ~ Worse	<p><u>Description</u> -All offly proof toilets are being used by people.</p> <table border="1"> <thead> <tr> <th rowspan="2">Condition</th> <th colspan="2">No. of HHs</th> </tr> <tr> <th>This week condition</th> <th>Previous week condition</th> </tr> </thead> <tbody> <tr> <td>Level 1</td> <td>42</td> <td>42</td> </tr> <tr> <td>Level 2</td> <td>21</td> <td>21</td> </tr> <tr> <td>Level 3</td> <td>0</td> <td>0</td> </tr> <tr> <td>Level 4</td> <td>0</td> <td>0</td> </tr> <tr> <td>No Toilet</td> <td>5</td> <td>5</td> </tr> </tbody> </table> <p><u>Evaluation Criteria</u>&gt;  <b>Level 1</b>            -No need to repair fly proof toilet            -No/rarely toilet unavailable  <b>Level 2</b>            -Need to repair fly proof toilet            -Rarely toilet unavailable  <b>Level 3</b>            -Need to repair fly proof toilet            -Often toilet unavailable  <b>Level 4</b>            -Need to repair urgently fly proof toilet            -Often toilet unavailable</p>	Condition	No. of HHs		This week condition	Previous week condition	Level 1	42	42	Level 2	21	21	Level 3	0	0	Level 4	0	0	No Toilet	5	5	<p><u>Photos</u></p>   
Condition	No. of HHs																							
	This week condition	Previous week condition																						
Level 1	42	42																						
Level 2	21	21																						
Level 3	0	0																						
Level 4	0	0																						
No Toilet	5	5																						
	(6). Electricity	Improved Same ~* Worse	<p><u>Description</u> -Electricity is coming regularly -Electric poles and transformers supported in good foundation.</p> <p><u>Photos</u></p>    																					

No	Item	Condition	Description and Photos																	
2	House Construction	No. of houses not completed (2)	<p><u>Description</u> - In HH No.5, the construction for kitchen, toilet and water stopped. Nobody lives.</p> <p><u>Photos</u></p> 																	
3	Living Status of PAPs (Sold house, renting, etc.)	<p><u>Description</u></p> <p>(1) House ownership (1)-1 No. of house that are owned by PAPs (4) (1)-2 No. of house that were sold (1)</p> <p>(2) Living condition (2)-1 No. of houses where PAPs live (3) (2)-2 No. of houses where not original PAPs live (2) (2)-3 No. of houses where nobody lives (4)</p>	<p>Location Map: See ANNEX.2</p>																	
4	Other issues	(1). Drainage condition for rain water in their compounds	<p><u>Description</u> -There are puddles and muddy areas in some compounds. -But most of the compounds are almost dry.</p> <table border="1" data-bbox="400 1323 987 1563"> <thead> <tr> <th rowspan="2">Condition</th> <th colspan="2">No. of HHs</th> </tr> <tr> <th>This week condition</th> <th>Previous week condition</th> </tr> </thead> <tbody> <tr> <td>Level 1</td> <td>15</td> <td>10</td> </tr> <tr> <td>Level 2</td> <td>36</td> <td>18</td> </tr> <tr> <td>Level 3</td> <td>16</td> <td>19</td> </tr> <tr> <td>Level 4</td> <td>1</td> <td>21</td> </tr> </tbody> </table> <p><u>Evaluation Criteria</u>&gt;</p> <p><b>Level 1</b> -No mud and no standing water with their drainage system in their compound</p> <p><b>Level 2</b> -No mud and no standing water in their compound</p> <p><b>Level 3</b> -Some or little mud and standing water in their compound</p> <p><b>Level 4</b> -A lot of mud and standing water in their compound</p>	Condition	No. of HHs		This week condition	Previous week condition	Level 1	15	10	Level 2	36	18	Level 3	16	19	Level 4	1	21
Condition	No. of HHs																			
	This week condition	Previous week condition																		
Level 1	15	10																		
Level 2	36	18																		
Level 3	16	19																		
Level 4	1	21																		





4 (2)  
Plantation

Description

-In front of their compounds, they planted shady trees, fruit trees, vegetable and floral plants.

Type	No. of HHs	Remarks
Shady tree	12	Albizia, Indian almond, etc. HH No. 2, 3, 14, 19, 20, 21, 25, 27, 29, 32, 41 and 65
Fruit tree	24	Banana, Mango, sugarcane, coconut, citrus, HH No. 2, 3, 4, 7, 8, 9, 11, 17, 21, 24, 25, 27, 33, 37, 38, 39, 41, 43, 45, 46, 47, 48, 54 and 65
Vegetable	10	Spices, peas, roselle, etc. HH No. 2, 23, 25, 27, 38, 39, 40, 42, 45 and 63
Floral plant	20	Many species. HH No. 29, 14, 15, 17, 21, 23, 27, 32, 33, 38, 39, 40, 41, 42, 43, 47, 48, 58 and 65

Photos





4 (3)Livestock

Description

-They are raising chicken, ducks, goats, pigs and cows.  
 -Even though they have cows, they do not keep their cows in relocation site they keep in their farms or other places.

Type	No. of HHs	Remarks
Cow	5	HH No.3, 18, 42, 47 and 54
Pig	1	HH No. 2
Goat	2	HH No.50 and 51
Chicken and ducks	15	HH No.4, 8, 12, 14, 28, 30, 32, 41, 47, 50, 51, 52, 55, 56 and 62

Photos



5 Remarks

-



