

















Biweekly Field Report

Surveyor Zaw La  
 Date visited 11 Apr 2018  
 Time visited 13: 15 am

Weather Condition Sunny  
 The last time of heavy raining Oct, 2017

No	Item	Condition	Description and Photos
1	(1) Well	Improved <input type="checkbox"/> Same <input checked="" type="checkbox"/> * Worse <input type="checkbox"/> *as last week	– Water from two open-wells is clean and can be used for drinking and living. There are eleven tube wells in the relocation site. People mainly use water from pipeline water distribution system so that no body use the tube wells and JET asked them to let know if the tube wells are need to be repaired.
			<div style="display: flex; flex-wrap: wrap;"> <div style="width: 50%; text-align: center;">  <p>Open Well No. 1</p> </div> <div style="width: 50%; text-align: center;">  <p>Open Well No. 2</p> </div> <div style="width: 50%; text-align: center;">  <p>Tube Well No. 1</p> </div> <div style="width: 50%; text-align: center;">  <p>Tube Well No.2</p> </div> <div style="width: 50%; text-align: center;">  <p>Tube Well No.3</p> </div> <div style="width: 50%; text-align: center;">  <p>Tube Well No.4</p> </div> <div style="width: 50%; text-align: center;">  <p>Tube Well No.5</p> </div> <div style="width: 50%; text-align: center;">  <p>Tube Well No.10</p> </div> </div>

			 <p>Tube Well No.7</p>	 <p>Tube Well No.6</p>
(2) Drainage	Improved <input type="checkbox"/> Same <input checked="" type="checkbox"/> * Worse <input type="checkbox"/> <i>*as last week</i>	<p>– There is no water in the drainage canals at the moment.</p> <p><b>Photos</b></p>	 <p>Drain at the corner of Main Road A and B</p>	 <p>Drain exit at the corner of Site village road and 2<sup>nd</sup> street</p>
			 <p>Drain exit at the corner of Site village road and 3<sup>rd</sup> street</p>	 <p>Drain exit at the corner of Site village road and Main Road C</p>
(3) Road	Improved <input type="checkbox"/> Same <input checked="" type="checkbox"/> * Worse <input type="checkbox"/> <i>*as last week</i>	<p>– All the roads are dry and no problem for walking.</p> <p><b>Photos</b></p>	 <p>Main Road - B</p>	 <p>1<sup>st</sup> Street</p>

			 <p>2<sup>nd</sup> Street Upper Block</p>	 <p>2<sup>nd</sup> Street Lower Block</p>
			 <p>3<sup>rd</sup> Street Upper Block</p>	 <p>3<sup>rd</sup> Street Lower Block</p>
			 <p>4<sup>th</sup> Street Upper Block</p>	 <p>4<sup>th</sup> Street Lower Block</p>
			 <p>5<sup>th</sup> Street</p>	 <p>6<sup>th</sup> Street</p>
			 <p>7<sup>th</sup> Street</p>	 <p>Site Village Road</p>





<p>(4) Garbage Condition</p>	<p>Improved <input type="checkbox"/> Same <input checked="" type="checkbox"/>* Worse <input type="checkbox"/> <i>*as last week</i></p>	<ul style="list-style-type: none"> <li>– People throw the trash at the corner of road, beside the creek and even in front of their houses before they got enough garbage bins.</li> <li>– There are fourteen garbage bins are provided and they are kept the corner of each road and some garbage bins are full and there are some trashes beside the creek.</li> </ul>	
<p><b>Photos</b></p>			
 <p>Rubbish bin at the corner of Main Road B and Road No. 1</p>		 <p>Rubbish bin at the corner of Main Road B and Road No. 2</p>	
 <p>Rubbish bin at the corner of Main Road B and Road No. 3</p>		 <p>Rubbish bin at the corner of Main Road B and Road No. 4</p>	
		 <p>Rubbish bin at Main Road - C</p>	 <p>Rubbish bin at the corner of Creek Road and 5<sup>th</sup> Street</p>
		 <p>Rubbish at the creek near 1st street</p>	 <p>Rubbish at the creek near 2nd street</p>











Rubbish at the creek near Main Road C








Rubbish at the creek near 6<sup>th</sup> Street

<p>(5) Fly proof toilet</p>	<p>Improved <input type="checkbox"/>          Same <input checked="" type="checkbox"/>*          Worse <input type="checkbox"/>  <i>*as last week</i></p>	<ul style="list-style-type: none"> <li>- All of the fly proof toilets are used by people.</li> <li>- No serious problem for toilet for the time being.</li> </ul> <table border="1" data-bbox="552 208 1235 506"> <thead> <tr> <th rowspan="2">Condition</th> <th colspan="2">No. of HHs</th> </tr> <tr> <th>This week condition</th> <th>Previous week condition</th> </tr> </thead> <tbody> <tr> <td>Level 1</td> <td>6</td> <td>6</td> </tr> <tr> <td>Level 2</td> <td>84</td> <td>84</td> </tr> <tr> <td>Level 3</td> <td>0</td> <td>0</td> </tr> <tr> <td>Level 4</td> <td>0</td> <td>0</td> </tr> <tr> <td>No Toilet</td> <td>0</td> <td>0</td> </tr> </tbody> </table> <p><b>&lt;Evaluation Criteria&gt;</b></p> <p><b>Level 1</b></p> <ul style="list-style-type: none"> <li>- Fly proof toilet is not needed to be repaired.</li> <li>-No/rarely toilet unavailable</li> </ul> <p><b>Level 2</b></p> <ul style="list-style-type: none"> <li>- Fly proof toilet is needed to be repaired.</li> <li>-Rarely toilet unavailable</li> </ul> <p><b>Level 3</b></p> <ul style="list-style-type: none"> <li>-- Fly proof toilet is needed to be repaired.</li> <li>-Often toilet unavailable</li> <li>-As the result of filling the soil and also due to the heavy rain, some toilets are inconvenience to use.</li> </ul> <p><b>Level 4</b></p> <ul style="list-style-type: none"> <li>- Fly proof toilet is urgently needed to be repaired.</li> <li>-Often toilet unavailable</li> </ul> <p><b>Photos</b></p> <div style="display: flex; flex-wrap: wrap;"> <div style="width: 50%; text-align: center;">  <p>House No. 81</p> </div> <div style="width: 50%; text-align: center;">  <p>House No. 37</p> </div> <div style="width: 50%; text-align: center;">  <p>House No. 31</p> </div> <div style="width: 50%; text-align: center;">  <p>House No. 21</p> </div> </div>	Condition	No. of HHs		This week condition	Previous week condition	Level 1	6	6	Level 2	84	84	Level 3	0	0	Level 4	0	0	No Toilet	0	0
Condition	No. of HHs																					
	This week condition	Previous week condition																				
Level 1	6	6																				
Level 2	84	84																				
Level 3	0	0																				
Level 4	0	0																				
No Toilet	0	0																				
<p>(6) Electricity</p>	<p>Improved <input type="checkbox"/>          Same <input checked="" type="checkbox"/>*          Worse <input type="checkbox"/>  <i>*as last week</i></p>	<ul style="list-style-type: none"> <li>- Electricity comes regularly.</li> <li>- Electric poles and transformer are being supported with a good foundation.</li> </ul> <p><b>Photos</b></p>																				

			 <p>Transformer No. 1</p>	 <p>Transformer No. 2</p>
			 <p>Transformer No. 3</p>	 <p>Electricity pole at the corner of Main Road B and Road No. 3</p>

No	Item	Condition	Description and Photos
2	(1)House Construct-ion	No. of houses not completed (4)	<ul style="list-style-type: none"> <li>– House No.9, there are three houses that planned to build in plot number 9 and 10 as the plots are owned by father and son. The two houses finished construction and left one.</li> <li>– House No.64, the house construction seems to be stopped.</li> <li>– House No. 78, the house need to be carried on construction, however PAPs are living now.</li> <li>– House No. 66, the house construction for first floor is finish and the second floor is need to be carried on.</li> </ul> <p><b>Photos</b></p>  <p>House No. 9</p>  <p>House No. 64</p>  <p>House No. 78</p>  <p>House No. 66</p>

3	Other Issues																			
	(1). Drainage condition for rain water in their compounds	<p><u>Description</u></p> <table border="1" data-bbox="560 208 1145 465"> <thead> <tr> <th rowspan="2">Condition</th> <th colspan="2">No. of HHs</th> </tr> <tr> <th>This week condition</th> <th>Previous week condition</th> </tr> </thead> <tbody> <tr> <td>Level 1</td> <td>63</td> <td>63</td> </tr> <tr> <td>Level 2</td> <td>5</td> <td>5</td> </tr> <tr> <td>Level 3</td> <td>0</td> <td>0</td> </tr> <tr> <td>Level 4</td> <td>0</td> <td>0</td> </tr> </tbody> </table> <p><b>&lt;Evaluation Criteria&gt;</b></p> <p><b>Level 1</b> -No mud and no standing water with their own drainage system in their compound</p> <p><b>Level 2</b> -No mud and no standing water in their compound</p> <p><b>Level 3</b> - Some or little mud and standing water in their compound</p> <p><b>Level 4</b> -A lot of mud and standing water in their compound</p> <p><u>Photos</u></p> <div data-bbox="560 949 1007 1263"> <p>Level 1</p>  <p>House No. 31</p> </div> <div data-bbox="1007 949 1449 1263"> <p>Level 2</p>  <p>House No. 19</p> </div> <div data-bbox="560 1263 1007 1592"> <p>Level 2</p>  <p>House No. 47</p> </div> <div data-bbox="1007 1263 1449 1592"> <p>Level 3</p>  <p>House No. 74</p> </div> <div data-bbox="560 1592 1007 1957"> <p>Level 3</p>  <p>House No. 75</p> </div>		Condition	No. of HHs		This week condition	Previous week condition	Level 1	63	63	Level 2	5	5	Level 3	0	0	Level 4	0	0
Condition	No. of HHs																			
	This week condition	Previous week condition																		
Level 1	63	63																		
Level 2	5	5																		
Level 3	0	0																		
Level 4	0	0																		



(2) Plantation


- In front of their compounds, the people planted shady trees, fruit trees, vegetables and floral plants.



Description

-In front of their compounds, the people planted shady trees, fruit trees, vegetables and floral plants.

Type	No. of HHs	Remarks
Shady tree	15	Albizzia, Indian almond, neem tree, etc. HH No. 20, 40, 43, 48, 51, 57, 59, 61, 62, 67, 69, 72, 73, 77, 85
Fruit tree	37	Banana, Mango, sugarcane, coconut, citrus, jack fruit etc. HH No. 3, 15, 17, 20,21, 23, 28, 30, 31, 32, 34, 37, 40, 41, 48, 51, 52, 55, 57, 58, 59, 61, 62, 63, 67, 68, 70, 71, 72, 73, 77, 78, 82, 85, 86, 88
Vegetable	20	Chili, tomato, bitter gourd, Roselle, gourd, basils, eggplant etc. HH No. 12, 17, 21, 41, 49, 58, 59, 61, 62, 63, 67, 68, 70, 71, 72, 73, 77, 82, 85, 86
Floral plant	31	Jasmine, poinsettia, orchid, kiss me quick, etc. HH No. 3, 5, 6, 8, 10, 12, 13, 14, 17, 20, 21, 22, 23, 29, 30, 31, 32, 46, 48, 58, 59, 61, 62, 65, 67, 68, 69, 72, 77, 78, 86

Photos,



(3) Livestock	<b>Description</b> -The people are raising chicken, geese, ducks and pigs.													
	<table border="1"> <thead> <tr> <th>Type</th> <th>No. of HHs</th> <th>Remarks</th> </tr> </thead> <tbody> <tr> <td>Chicken</td> <td>6</td> <td>HH No. 13, 14, 21, 59, 67, 78</td> </tr> <tr> <td>Pig</td> <td>3</td> <td>HH No. 2, 21, 56</td> </tr> <tr> <td>Goose</td> <td>2</td> <td>HH No. 40, 67</td> </tr> </tbody> </table>	Type	No. of HHs	Remarks	Chicken	6	HH No. 13, 14, 21, 59, 67, 78	Pig	3	HH No. 2, 21, 56	Goose	2	HH No. 40, 67	
Type	No. of HHs	Remarks												
Chicken	6	HH No. 13, 14, 21, 59, 67, 78												
Pig	3	HH No. 2, 21, 56												
Goose	2	HH No. 40, 67												
	<b>Photos</b>													
	 <p>House No. 67</p>	 <p>House No. 2</p>												