



























Biweekly Field Report

Surveyor Zaw La
 Date visited 8 Jun 2018
 Time visited 16 : 15 am





Weather Condition Cloudy
 The last time of heavy raining Yesterday





No	Item	Condition	Description and Photos
1	(1) Well	Improved <input type="checkbox"/> Same <input checked="" type="checkbox"/> * Worse <input type="checkbox"/> <i>*as last week</i>	– Water from two open-wells is clean and can be used for drinking and living. There are eleven tube wells in the relocation site. People mainly use water from pipeline water distribution system so that no body use the tube wells and JET asked them to let know if the tube wells are needed to repair.
			<div style="display: flex; flex-wrap: wrap;"> <div style="width: 50%; text-align: center;">  <p>Open Well No. 1</p> </div> <div style="width: 50%; text-align: center;">  <p>Open Well No. 2</p> </div> <div style="width: 50%; text-align: center;">  <p>Tube Well No. 1</p> </div> <div style="width: 50%; text-align: center;">  <p>Tube Well No. 2</p> </div> <div style="width: 50%; text-align: center;">  <p>Tube Well No. 3</p> </div> <div style="width: 50%; text-align: center;">  <p>Tube Well No. 4</p> </div> <div style="width: 50%; text-align: center;">  <p>Tube Well No. 5</p> </div> <div style="width: 50%; text-align: center;">  <p>Tube Well No. 10</p> </div> </div>





			 <div data-bbox="555 392 790 448" style="border: 1px solid black; padding: 2px;">Tube Well No.7</div>	 <div data-bbox="992 392 1220 448" style="border: 1px solid black; padding: 2px;">Tube Well No.6</div>
(2) Drainage	Improved <input type="checkbox"/> Same <input checked="" type="checkbox"/> * Worse <input type="checkbox"/> <i>*as last week</i>	<p>– There is a little water in the drainage canals at the moment.</p> <p>Photos</p>	 <div data-bbox="555 840 976 918" style="border: 1px solid black; padding: 2px;">Drain at the corner of Main Road A and B</div>	 <div data-bbox="992 840 1417 918" style="border: 1px solid black; padding: 2px;">Drain exit at the corner of Site village road and 2nd street</div>
			 <div data-bbox="555 1232 976 1310" style="border: 1px solid black; padding: 2px;">Drain exit at the corner of Site village road and 3rd</div>	 <div data-bbox="992 1232 1417 1310" style="border: 1px solid black; padding: 2px;">Drain exit at the corner of Site village road and Main Road C</div>
(3) Road	Improved <input type="checkbox"/> Same <input checked="" type="checkbox"/> * Worse <input type="checkbox"/> <i>*as last week</i>	<p>– All the roads are dry and no problem for walking.</p> <p>Photos</p>	 <div data-bbox="555 1702 742 1747" style="border: 1px solid black; padding: 2px;">Main Road - B</div>	 <div data-bbox="992 1702 1189 1747" style="border: 1px solid black; padding: 2px;">1st Street</div>







			 <p>2nd Street Upper Block</p>	 <p>2nd Street Lower Block</p>
			 <p>3rd Street Upper Block</p>	 <p>3rd Street Lower Block</p>
			 <p>4th Street Upper Block</p>	 <p>4th Street Lower Block</p>
			 <p>5th Street</p>	 <p>6th Street</p>
			 <p>7th Street</p>	 <p>Site Village Road</p>

	(4) Garbage Condition	Improved <input type="checkbox"/> Same <input checked="" type="checkbox"/> * Worse <input type="checkbox"/> <i>*as last week</i>	<ul style="list-style-type: none"> – People throw garbage beside the creek and even in front of their houses before they got enough garbage bins. – There are fourteen garbage bins are provided and they are kept at the corner of each road until the end of April and now all the garbage bins are kept in the communal compound near side road C by PAP community leader. During this raining season, people must keep garbage in its own house until the garbage collection car is coming. <p>Photos</p>
			<div data-bbox="555 450 967 745" data-label="Image"> </div> <div data-bbox="555 745 967 824" data-label="Caption"> <p>Rubbish at the creek near 1st street</p> </div> <div data-bbox="999 450 1410 745" data-label="Image"> </div> <div data-bbox="999 745 1410 824" data-label="Caption"> <p>Rubbish at the creek near 2nd street</p> </div>
			<div data-bbox="555 869 967 1144" data-label="Image"> </div> <div data-bbox="555 1144 967 1227" data-label="Caption"> <p>Rubbish at the creek near Main Road C</p> </div> <div data-bbox="999 869 1410 1144" data-label="Image"> </div> <div data-bbox="999 1144 1410 1227" data-label="Caption"> <p>Rubbish at the creek near 6th Street</p> </div>

<p>(5) Fly proof toilet</p>	<p>Improved <input type="checkbox"/> Same <input checked="" type="checkbox"/>* Worse <input type="checkbox"/> <i>*as last week</i></p>	<ul style="list-style-type: none"> - All of the fly proof toilets are used by people. - The four toilets had been repaired since April and the rest ones are repairing now by two local constructors from PAPs. <table border="1" data-bbox="550 241 1233 539"> <thead> <tr> <th rowspan="2">Condition</th> <th colspan="2">No. of HHs</th> </tr> <tr> <th>This week condition</th> <th>Previous week condition</th> </tr> </thead> <tbody> <tr> <td>Level 1</td> <td>59</td> <td>6</td> </tr> <tr> <td>Level 2</td> <td>32</td> <td>85</td> </tr> <tr> <td>Level 3</td> <td>0</td> <td>0</td> </tr> <tr> <td>Level 4</td> <td>0</td> <td>0</td> </tr> <tr> <td>No Toilet</td> <td>0</td> <td>0</td> </tr> </tbody> </table> <p><Evaluation Criteria></p> <p>Level 1</p> <ul style="list-style-type: none"> - Fly proof toilet is not needed to be repaired. -No/rarely toilet unavailable <p>Level 2</p> <ul style="list-style-type: none"> - Fly proof toilet is needed to be repaired. -Rarely toilet unavailable <p>Level 3</p> <ul style="list-style-type: none"> -- Fly proof toilet is needed to be repaired. -Often toilet unavailable -As the result of filling the soil and also due to the heavy rain, some toilets are inconvenience to use. <p>Level 4</p> <ul style="list-style-type: none"> - Fly proof toilet is urgently needed to be repaired. -Often toilet unavailable <p>Photos</p> <div style="display: flex; flex-wrap: wrap;"> <div style="width: 50%; text-align: center;">  <p>House No. 81</p> </div> <div style="width: 50%; text-align: center;">  <p>House No. 37</p> </div> <div style="width: 50%; text-align: center;">  <p>House No. 31</p> </div> <div style="width: 50%; text-align: center;">  <p>House No. 21</p> </div> </div>	Condition	No. of HHs		This week condition	Previous week condition	Level 1	59	6	Level 2	32	85	Level 3	0	0	Level 4	0	0	No Toilet	0	0
Condition	No. of HHs																					
	This week condition	Previous week condition																				
Level 1	59	6																				
Level 2	32	85																				
Level 3	0	0																				
Level 4	0	0																				
No Toilet	0	0																				
<p>(6) Electricity</p>	<p>Improved <input type="checkbox"/> Same <input checked="" type="checkbox"/>* Worse <input type="checkbox"/> <i>*as last week</i></p>	<ul style="list-style-type: none"> - Electricity comes regularly. - Electric poles and transformer are being supported with a good foundation. - There are some pieces of wood under an electric pole of main road B need to be cleaned. <p>Photos</p>																				

			 <p>Transformer No. 1</p>	 <p>Transformer No. 2</p>
			 <p>Transformer No. 3</p>	 <p>Electricity pole at the corner of Main Road B and Road No. 3</p>

No	Item	Condition	Description and Photos
2	(1)House Construct-ion	No. of houses not completed (4)	<ul style="list-style-type: none"> – House No.9, there are three houses that planned to build in plot number 9 and 10 as the plots are owned by father and son. The two houses finished construction and left one. – House No.64, the house construction seems to be stopped. – House No. 78, the house need to be carried on construction, however PAPs are living now. – House No. 66, the house construction for first floor has been finished and the second floor is needed to be carried on. <p>Photos</p>  <p>House No. 9</p>  <p>House No. 64</p>  <p>House No. 78</p>  <p>House No. 66</p>

3	Other Issues																			
	(1). Drainage condition for rain water in their compounds	<p><u>Description</u></p> <table border="1" data-bbox="560 208 1145 465"> <thead> <tr> <th rowspan="2">Condition</th> <th colspan="2">No. of HHs</th> </tr> <tr> <th>This week condition</th> <th>Previous week condition</th> </tr> </thead> <tbody> <tr> <td>Level 1</td> <td>87</td> <td>87</td> </tr> <tr> <td>Level 2</td> <td>3</td> <td>4</td> </tr> <tr> <td>Level 3</td> <td>0</td> <td>0</td> </tr> <tr> <td>Level 4</td> <td>1</td> <td>0</td> </tr> </tbody> </table> <p><Evaluation Criteria></p> <p>Level 1 -No mud and no standing water with their own drainage system in their compound</p> <p>Level 2 -No mud and no standing water in their compound</p> <p>Level 3 - Some or little mud and standing water in their compound</p> <p>Level 4 -A lot of mud and standing water in their compound</p> <p>Photos</p> <div data-bbox="560 949 999 1263"> <p>Level 1</p>  <p>House No. 31</p> </div> <div data-bbox="1015 949 1449 1263"> <p>Level 2</p>  <p>House No. 19</p> </div> <div data-bbox="560 1274 999 1588"> <p>Level 2</p>  <p>House No. 47</p> </div> <div data-bbox="1015 1274 1449 1588"> <p>Level 4</p>  <p>House No. 64</p> </div> <div data-bbox="560 1632 999 1946"> <p>Level 3</p>  <p>House No. 75</p> </div>		Condition	No. of HHs		This week condition	Previous week condition	Level 1	87	87	Level 2	3	4	Level 3	0	0	Level 4	1	0
Condition	No. of HHs																			
	This week condition	Previous week condition																		
Level 1	87	87																		
Level 2	3	4																		
Level 3	0	0																		
Level 4	1	0																		
		<div data-bbox="560 1632 999 1946"> <p>Level 3</p>  <p>House No. 75</p> </div>																		

(2) Plantation

- In front of their compounds, the people planted shady trees, fruit trees, vegetables and floral plants.



Description

-In front of their compounds, the people planted shady trees, fruit trees, vegetables and floral plants.

Type	No. of HHs	Remarks
Shady tree	15	Albizzia, Indian almond, neem tree, etc. HH No. 20, 40, 43, 48, 51, 57, 59, 61, 62, 67, 69, 72, 73, 77, 85
Fruit tree	37	Banana, Mango, sugarcane, coconut, citrus, jack fruit etc. HH No. 3, 15, 17, 20,21, 23, 28, 30, 31, 32, 34, 37, 40, 41, 48, 51, 52, 55, 57, 58, 59, 61, 62, 63, 67, 68, 70, 71, 72, 73, 77, 78, 82, 85, 86, 88
Vegetable	20	Chili, tomato, bitter gourd, Roselle, gourd, basils, eggplant etc. HH No. 12, 17, 21, 41, 49, 58, 59, 61, 62, 63, 67, 68, 70, 71, 72, 73, 77, 82, 85, 86
Floral plant	31	Jasmine, poinsettia, orchid, kiss me quick, etc. HH No. 3, 5, 6, 8, 10, 12, 13, 14, 17, 20, 21, 22, 23, 29, 30, 31, 32, 46, 48, 58, 59, 61, 62, 65, 67, 68, 69, 72, 77, 78, 86

Photos,



(3) Livestock	Description -The people are raising chicken, geese, ducks and pigs.												
	<table border="1"> <thead> <tr> <th>Type</th> <th>No. of HHs</th> <th>Remarks</th> </tr> </thead> <tbody> <tr> <td>Chicken</td> <td>6</td> <td>HH No. 13, 14, 21, 59, 67, 78</td> </tr> <tr> <td>Pig</td> <td>3</td> <td>HH No. 2, 21, 56</td> </tr> <tr> <td>Goose</td> <td>2</td> <td>HH No. 40, 67</td> </tr> </tbody> </table>	Type	No. of HHs	Remarks	Chicken	6	HH No. 13, 14, 21, 59, 67, 78	Pig	3	HH No. 2, 21, 56	Goose	2	HH No. 40, 67
Type	No. of HHs	Remarks											
Chicken	6	HH No. 13, 14, 21, 59, 67, 78											
Pig	3	HH No. 2, 21, 56											
Goose	2	HH No. 40, 67											
	Photos												
	 <p>House No. 67</p>	 <p>House No. 12</p>											