

Weekly Field Report

No. 37





Surveyor: Zaw La

Date Visited: 16.7.2015





Time Visited: 14:30to 15:30



Weather Condition: Raining

The last time of heavy raining: - the whole day

No	Item	Condition	Description and Photos
1	Condition of -		
	(1). Well	Improved <input type="checkbox"/> Same <input checked="" type="checkbox"/> * Worse <input type="checkbox"/> <i>*as last week</i>	Description & Photos: -See ANNEX.1 - One of the wells is not very clean, but another well and all hand pumps are functioned well except the one near transformer, water is clean and water amount is enough to use as the raining season has been started and groundwater level is raising up. No problem for clean water at the moment.
	(2). <u>Drainage</u>	Improved <input type="checkbox"/> Same <input checked="" type="checkbox"/> * Worse <input type="checkbox"/> <i>*as last week</i>	<u>Description</u> -Water level in the drainage canals is about the same level as last week because there was small amount of rain almost the whole day. The stream along the drainage canal needs to be rehabilitated in next summer. <u>Photos</u> <div style="display: flex; flex-wrap: wrap; justify-content: space-around;"> <div style="text-align: center;">  <p>Near well No.1</p> </div> <div style="text-align: center;">  <p>Near HH No. 48</p> </div> <div style="text-align: center;">  <p>Near HH No. 1</p> </div> <div style="text-align: center;">  <p>Near garbage pit</p> </div> </div>










<p>(3). Road</p>	<p>Improved <input type="checkbox"/> Same <input checked="" type="checkbox"/>* Worse <input type="checkbox"/> <i>*as last week</i></p>	<p><u>Description</u> -The roads are being wet a bit and muddy in some areas but no problem for walking.</p> <p><u>Photos</u></p> <div style="display: flex; flex-wrap: wrap;"> <div style="width: 50%; text-align: center;"> <p>Front main road</p>  </div> <div style="width: 50%; text-align: center;"> <p>The right road of relocation site</p>  </div> <div style="width: 50%; text-align: center;"> <p>Middle road</p>  </div> <div style="width: 50%; text-align: center;"> <p>The left road of relocation site</p>  </div> </div>
------------------	---	--

<p>(4). Garbage Condition</p>	<p>Improved <input type="checkbox"/> Same <input checked="" type="checkbox"/>* Worse <input type="checkbox"/></p>	<p><u>Description</u> -Garbage pit is used by people. -Garbage pit is over full and it needs to be cleaned up. -There are some smells from garbage pit. -People throw garbage at the backside of Third Row.</p> <div style="display: flex;"> <div style="width: 50%; text-align: center;"> <p>Garbage pit</p>  </div> <div style="width: 50%; text-align: center;"> <p>Garbage pit</p>  </div> </div>
---------------------------------------	---	---





<p>No 1</p>	<p>Item (5). Fly proof toilet</p>	<p>Condition Improved <input type="checkbox"/> Same <input checked="" type="checkbox"/>* Worse <input type="checkbox"/> *as last week</p>	<p>Description -All of fly proof toilets are used by people.</p> <table border="1" data-bbox="597 579 992 896"> <thead> <tr> <th rowspan="2">Condition</th> <th colspan="2">No. of HHs</th> </tr> <tr> <th>This week condition</th> <th>Previous week condition</th> </tr> </thead> <tbody> <tr> <td>Level 1</td> <td>6</td> <td>6</td> </tr> <tr> <td>Level 2</td> <td>18</td> <td>18</td> </tr> <tr> <td>Level 3</td> <td>29</td> <td>29</td> </tr> <tr> <td>Level 4</td> <td>13</td> <td>13</td> </tr> <tr> <td>No Toilet</td> <td>2</td> <td>2</td> </tr> </tbody> </table> <p><Evaluation Criteria> Level 1 -No need to repair fly proof toilet -No/rarely toilet unavailable Level 2 -Need to repair fly proof toilet -Rarely toilet unavailable Level 3 -Need to repair fly proof toilet -Often toilet unavailable -As the result of filling the soil and also raining, some toilets are inconvenience to use. Level 4 -Need to repair urgently fly proof toilet -Often toilet unavailable -After filling the soil, some toilets need to be lifted up. (Remark: The toilet picture of level 4 has changed due to bamboo type and concrete type.)</p> <div style="display: flex; justify-content: space-around;"> <div data-bbox="609 1551 987 1835"> <p>Level 1 HH No. 6</p> </div> <div data-bbox="1019 1551 1398 1835"> <p>Level 2 HH No. 12</p> </div> </div>	Condition	No. of HHs		This week condition	Previous week condition	Level 1	6	6	Level 2	18	18	Level 3	29	29	Level 4	13	13	No Toilet	2	2
Condition	No. of HHs																						
	This week condition	Previous week condition																					
Level 1	6	6																					
Level 2	18	18																					
Level 3	29	29																					
Level 4	13	13																					
No Toilet	2	2																					

			<div style="display: flex; justify-content: space-around;"> <div style="text-align: center;"> <p>Level 3</p>  </div> <div style="text-align: center;"> <p>Level 4</p>  </div> </div>
(6). Electricity	Improved <input type="checkbox"/> Same <input checked="" type="checkbox"/> * Worse <input type="checkbox"/> <i>*as last week</i>	<u>Description</u> -Electricity comes regularly. -Electric poles and transformer are supported in good foundation. -But, there is a hole at an electric pole which was hit by a truck car. The electric pole needs to be renovated. <u>Photos</u>	<div style="display: flex; justify-content: space-around;"> <div style="text-align: center;"> <p>In front of HH No. 24</p>  </div> <div style="text-align: center;"> <p>In front of HH No. 24</p>  </div> </div> <div style="display: flex; justify-content: space-around; margin-top: 10px;">   </div>
No	Item	Condition	Description and Photos
2	House Construct- ion	No. of houses not completed (2)	<u>Description</u> -Renovation of HH No.1 is finished. -HH No.5, the construction for kitchen, toilet and water tank seems to be started again. <div style="text-align: center; margin-top: 10px;"> <p>HH No. 5</p>  </div>

3	Living Status of PAPs (Sold house, renting, etc.)	<u>Description</u>
		(1) House ownership (1)-1 No. of house that are owned by PAPs (50) (1)-2 No. of house that were sold (18) (2) Living condition (2)-1 No. of houses where PAPs live (41) (2)-2 No. of houses where not original PAPs lives (22) (2)-3 No. of houses where nobody lives (5)
		Location Map: See ANNEX.2

4 Other issue

(1). Drainage condition for rain water in their compounds	<u>Description</u>																	
	-Rainy season has been started. -Most of the compounds are being wet.																	
	<table border="1"> <thead> <tr> <th rowspan="2">Condition</th> <th colspan="2">No. of HHs</th> </tr> <tr> <th>This week condition</th> <th>Previous week condition</th> </tr> </thead> <tbody> <tr> <td>Level 1</td> <td>14</td> <td>14</td> </tr> <tr> <td>Level 2</td> <td>30</td> <td>30</td> </tr> <tr> <td>Level 3</td> <td>20</td> <td>20</td> </tr> <tr> <td>Level 4</td> <td>4</td> <td>4</td> </tr> </tbody> </table>	Condition	No. of HHs		This week condition	Previous week condition	Level 1	14	14	Level 2	30	30	Level 3	20	20	Level 4	4	4
Condition	No. of HHs																	
	This week condition	Previous week condition																
Level 1	14	14																
Level 2	30	30																
Level 3	20	20																
Level 4	4	4																
	<p><Evaluation Criteria></p> <p>Level 1 -No mud and no standing water with their own drainage system in their compound</p> <p>Level 2 -No mud and no standing water in their compound</p> <p>Level 3 - Some or little mud and standing water in their compound</p> <p>Level 4 -A lot of mud and standing water in their compound</p> <p><u>Photos</u></p>																	
	<div style="display: flex; justify-content: space-around;"> <div style="text-align: center;">  <p>HH No. 47 Level 1</p> </div> <div style="text-align: center;">  <p>HH No. 47 Level 3</p> </div> </div>																	



4 (2) Plantation

Description
 -In front of their compounds, they planted shady trees, fruit trees, vegetables and floral plants.

Type	No. of HHs	Remarks
Shady tree	12	Albizzia, Indian almond, etc. HH No. 2, 3, 14, 19, 20, 21, 25, 27, 29, 32, 41 and 65
Fruit tree	24	Banana, Mango, sugarcane, coconut, citrus, etc. HH No. 2, 3, 4, 7, 8, 9, 11, 17, 21,24, 25, 27, 33, 37, 38, 39, 41, 43, 45, 46, 47, 48, 54 and 65
Vegetable	10	Spices, peas, roselle, etc. HH No. 22, 23, 25, 27, 38, 39, 40, 42,45 and 63
Floral plant	20	Many species. HH No. 2, 9, 14, 15, 17,21, 23, 27, 32, 33, 38, 39, 40, 41, 42, 43, 47, 48, 58 and 65



4 (3) Livestock

Description
 -They are raising chicken, ducks, goats, pigs and cows.

-Even though they have cows, they do not keep their cows in relocation site instead they keep in their farms or other places.

Type	No. of HHs	Remarks
Cow	5	HH No. 3, 18, 42, 47 and 54
Pig	-	-
Goat	1	HH.47
Chicken and ducks	15	HH No. 4, 8, 12, 14, 28, 30, 32, 41, 47, 50, 51, 52, 55, 56 and 62

Photos



ANNEX.1

As of 16.7.2015

Water is clean and people nearby are using it for drinking and living use. A pulley wheel, bucket and a rope have been set up but the rope seems to be thin and it is better to be changed with thick one for the better use.



Water is not very clean with the rain and the well has to be repaired again after the raining season. A pulley wheel, bucket and a rope have set already but the rope seems to be thin and it is better to change with a thick one for the better use.




This hand pump is being also functioned very well. Water is clean and everyone living nearby is using this hand pump. Now the raining season has started and the groundwater level is raising up and therefore the amount of water is enough to use.



This hand pump is functioned very well. Water is clean and everyone nearby is using this hand pump.

This hand pump is functioned very well. Water is clean and everyone nearby using this hand pump for drinking water and living use.

Hand pump isn't functioned.



- Closed Well
- New Well (Hand pump)
- Open Well
- Hand Pump
- Private Well

This hand pump is functioned very well. Water is clean and everyone living nearby is using this hand pump. Moreover water filter tank for remove the smell of iron has been set up beside the hand pump. There is no smell of iron and people enjoy water for drinking and living use.

