

Weekly Field Report

No. 35

Surveyor: Zaw La

Date Visited: 29.6.2015

Time Visited: 15:30to 16:30

Weather Condition: Sunny

The last time of heavy raining: - last night

No	Item	Condition	Description and Photos
1	Condition of -		
	(1). Well	Improved <input type="checkbox"/> Same <input type="checkbox"/> Worse <input checked="" type="checkbox"/> <i>*as last week</i>	Description & Photos: -See ANNEX.1 - One of the wells is not very clean, but another well and all hand pumps are functioned well except the one near transformer, water is clean and water amount is enough to use as the raining season has been started and groundwater level is raising up. No problem for clean water at the moment.
	(2). <u>Drainage</u>	Improved <input type="checkbox"/> Same <input type="checkbox"/> Worse <input checked="" type="checkbox"/> <i>*as last week</i>	<u>Description</u> -Water level in the drainage canal higher than last week because there was a heavy rain this morning. The stream along the drainage may need to be rehabilitated in order to improve the water-flow in coming summer. <u>Photos</u> <div style="display: flex; flex-wrap: wrap;"> <div style="width: 50%; text-align: center;">  <p>Near well No. 1</p> </div> <div style="width: 50%; text-align: center;">  <p>Near HH No. 48</p> </div> <div style="width: 50%; text-align: center;">  <p>Near HH No. 1</p> </div> <div style="width: 50%; text-align: center;">  <p>Near garbage pit</p> </div> <div style="width: 50%; text-align: center;">  <p>In front of HH No. 1</p> </div> </div>

	(3). Road	Improved <input checked="" type="checkbox"/> * Same <input type="checkbox"/> Worse <input type="checkbox"/> <i>*as last week</i>	<u>Description</u> -The roads are being wet and muddy in some area but no problem for walking. The cleaning work for all roads had been done.
			<u>Photos</u> <div style="display: flex; flex-wrap: wrap; justify-content: space-around;"> <div style="text-align: center; margin: 5px;"> <p>In front road</p>  </div> <div style="text-align: center; margin: 5px;"> <p>Near transformer road</p>  </div> <div style="text-align: center; margin: 5px;"> <p>The middle road</p>  </div> <div style="text-align: center; margin: 5px;"> <p>Near garbage road</p>  </div> </div>
	(4). Garbage Condition	Improved <input type="checkbox"/> Same <input checked="" type="checkbox"/> * Worse <input type="checkbox"/>	<u>Description</u> -Garbage pit is used by people. -Garbage pit is over full and it needs to be cleaned up. -There are some smells from garbage pit. -People throw garbage at the backside of Third Row.



No	Item	Condition	Description	Photos																				
1	(5). Fly proof toilet	Improved <input type="checkbox"/> Same <input checked="" type="checkbox"/> * Worse <input type="checkbox"/> <i>*as last week</i>	<p>-All of fly proof toilets are used by people.</p> <table border="1" data-bbox="634 331 1027 653"> <thead> <tr> <th rowspan="2">Condition</th> <th colspan="2">No. of HHs</th> </tr> <tr> <th>This week condition</th> <th>Previous week condition</th> </tr> </thead> <tbody> <tr> <td>Level 1</td> <td>6</td> <td>6</td> </tr> <tr> <td>Level 2</td> <td>18</td> <td>18</td> </tr> <tr> <td>Level 3</td> <td>29</td> <td>29</td> </tr> <tr> <td>Level 4</td> <td>13</td> <td>13</td> </tr> <tr> <td>No Toilet</td> <td>2</td> <td>2</td> </tr> </tbody> </table> <p><Evaluation Criteria> Level 1 -No need to repair fly proof toilet -No/rarely toilet unavailable Level 2 -Need to repair fly proof toilet -Rarely toilet unavailable Level 3 -Need to repair fly proof toilet -Often toilet unavailable -As the result of filling the soil and also raining, some toilets are inconvenience to use. Level 4 -Need to repair urgently fly proof toilet -Often toilet unavailable -After filling the soil, some toilets need to be lifted up.</p>	Condition	No. of HHs		This week condition	Previous week condition	Level 1	6	6	Level 2	18	18	Level 3	29	29	Level 4	13	13	No Toilet	2	2	
Condition	No. of HHs																							
	This week condition	Previous week condition																						
Level 1	6	6																						
Level 2	18	18																						
Level 3	29	29																						
Level 4	13	13																						
No Toilet	2	2																						
	(6). Electricity	Improved <input type="checkbox"/> Same <input type="checkbox"/> Worse <input checked="" type="checkbox"/> * <i>*as last week</i>	<p>Description</p> <p>-Electricity comes regularly. -Electric poles and transformer are supported in good foundation. -But, there is a hole at an electric pole which was hit by a truck car. The electric pole need to be renovated.</p>																					

			<p><u>Photos</u></p>
--	--	--	----------------------

No	Item	Condition	Description and Photos
2	House Construction	No. of houses not completed (2)	<p><u>Description</u></p> <ul style="list-style-type: none"> -Renovation HH No.1 is finished. -HH No.5, the construction for kitchen, toilet and water tank seems to be started again. -Soil filling work has done for all the compounds of the PAP's. <p><u>Photos</u></p>

3	Living Status of PAPs (Sold house, renting, etc.)	<p><u>Description</u></p> <p>(1) House ownership</p> <ul style="list-style-type: none"> (1)-1 No. of house that are owned by PAPs (50) (+2 than last week) (1)-2 No. of house that were sold (18) (-2 than last week) <p>(2) Living condition</p> <ul style="list-style-type: none"> (2)-1 No. of houses where PAPs live (41) (+1 than last week) (2)-2 No. of houses where not original PAPs lives (22) (+1 than last week) (2)-3 No. of houses where nobody lives (5) (-2 than last week) <p>Location Map: See ANNEX.2</p>
---	---	---

--	--	--	--

4	<p>Other issues</p> <p>(1). Drainage condition for rain water in their compounds</p>	<p><u>Description</u></p> <p>-Rainy season has been started. -Most of the compounds are being wet. -The ground is soft as soil filling work had done last week.</p> <table border="1" data-bbox="456 373 1036 611"> <thead> <tr> <th rowspan="2">Condition</th> <th colspan="2">No. of HHs</th> </tr> <tr> <th>This week condition</th> <th>Previous week condition</th> </tr> </thead> <tbody> <tr> <td>Level 1</td> <td>14</td> <td>14</td> </tr> <tr> <td>Level 2</td> <td>30</td> <td>30</td> </tr> <tr> <td>Level 3</td> <td>20</td> <td>20</td> </tr> <tr> <td>Level 4</td> <td>4</td> <td>4</td> </tr> </tbody> </table> <p><Evaluation Criteria></p> <p>Level 1 -No mud and no standing water with their own drainage system in their compound</p> <p>Level 2 -No mud and no standing water in their compound</p> <p>Level 3 - Some or little mud and standing water in their compound</p> <p>Level 4 -A lot of mud and standing water in their compound</p> <div data-bbox="485 1010 948 1352">  </div> <div data-bbox="987 1010 1450 1352">  </div> <div data-bbox="485 1367 948 1709">  </div> <div data-bbox="987 1367 1450 1709">  </div> <p>The soil filling work has just finished, but the soil is still soft and need to wait time to be harded.</p>	Condition	No. of HHs		This week condition	Previous week condition	Level 1	14	14	Level 2	30	30	Level 3	20	20	Level 4	4	4
Condition	No. of HHs																		
	This week condition	Previous week condition																	
Level 1	14	14																	
Level 2	30	30																	
Level 3	20	20																	
Level 4	4	4																	
4	<p>(2) Plantation</p>	<p><u>Description</u></p> <p>-In front of their compounds, they planted shady trees, fruit trees, vegetables and floral plants.</p>																	

Type	No. of HHs	Remarks
Shady tree	12	Albizia, Indian almond, etc. HH No. 2, 3, 14, 19, 20, 21, 25, 27, 29, 32, 41 and 65
Fruit tree	24	Banana, Mango, sugarcane, coconut, citrus, etc. HH No. 2, 3, 4, 7, 8, 9, 11, 17, 21,24, 25, 27, 33, 37, 38, 39, 41, 43, 45, 46, 47, 48, 54 and 65
Vegetable	10	Spices, peas, Roselle, etc. HH No. 22, 23, 25, 27, 38, 39, 40, 42,45 and 63
Floral plant	20	Many species. HH No. 2, 9, 14, 15, 17,21, 23, 27, 32, 33, 38, 39, 40, 41, 42, 43, 47, 48, 58 and 65

Photos



4 (3) Livestock

Description

-They are raising chicken, ducks, goats, pigs and cows.
-Even though they have cows, they do not keep their cows in relocation site instead they keep in their farms or other places.

Type	No. of HHs	Remarks
Cow	5	HH No. 3, 18, 42, 47 and 54
Pig	-	-
Goat	1	HH.47
Chicken and ducks	15	HH No. 4, 8, 12, 14, 28, 30, 32, 41, 47, 50, 51, 52, 55, 56 and 62

		<p data-bbox="451 197 540 226"><u>Photos</u></p>  
5	Remarks	<p data-bbox="264 625 1451 724">For avoiding from flood, each of the PAPs' compounds are fenced by retaining wall, the poles of the houses are painted with water proofing paint or making concrete protection. Moreover each of the PAPs' compound are filled with the soil.</p>

ANNEX.1

As of 29.6.2015

Water is clean and people nearby are using it for drinking and living use. A pulley wheel, bucket and a rope have been set up but the rope seems to be thin and it is better to be changed with thick one for the better use.



This hand pump is functioned very well. Water is clean and everyone nearby is using this hand pump.

This hand pump is functioned very well. Water is clean and everyone nearby using this hand pump for drinking water and living use.

Hand pump isn't functioned.

The well is in good situation. No smell. Water is clean and people nearby are using it for drinking and living use. A pulley wheel, bucket and a rope have been set up but the road seems to be thin and it is better to be changed with a thick one for the better use.



This hand pump is also functioned very well. Water is clean and everyone living nearby is using this hand pump. Now the raining season has started and the groundwater level is raising up and therefore the amount of water is enough to use.

This hand pump is functioned very well. Water is clean and everyone living nearby is using this hand pump. Moreover water filter tank for remove the smell of iron has been set up beside the hand pump. There is no smell of iron and people enjoy water for drinking and living use.



- Closed Well
- New Well (Hand pump)
- Open Well
- Hand Pump

