

Weekly Field Report

No. 32


Surveyor: Zaw La

Date Visited: 10.6.2015






Time Visited: 15:00to 16:30


Weather Condition: Sunny


The last time of heavy raining: -





No	Item	Condition	Description and Photos
1	Condition of -		
	(1). Well	Improved <input checked="" type="checkbox"/> Same Worse <input type="checkbox"/> <i>*as last week</i>	Description & Photos: -See ANNEX.1 - Two wells and all hand pumps except near transformer are well functioned, water is clean and water amount is enough to use as the raining season is nearer and underground water level is raising up. Therefore no problem for clean water.
	(2). Drainage	Improved <input type="checkbox"/> Same <input checked="" type="checkbox"/> Worse <input type="checkbox"/> <i>*as last week</i>	<p><u>Description</u> -Water level in the drainage canal is increased a lot than last week because there was a heavy rain about two days ago. Though the drainage canal has increased with water the resident places are not much problem because the soil filling in each compound has done.</p> <p><u>Photos</u></p> 

	(3). Road	Improved <input type="checkbox"/> Same <input checked="" type="checkbox"/> * Worse <input type="checkbox"/> <i>*as last week</i>	<u>Description</u> -The roads are a bit wet and there are some muddy in the roads but no problem for walking so far. As mentioned in the pictures, the roads haven't clean up yet after filling the soil to residents' lots.
			<u>Photos</u> 
	(4). Garbage Condition	Improved <input type="checkbox"/> Same <input checked="" type="checkbox"/> * Worse <input type="checkbox"/>	<u>Description</u> -Garbage pit is used by people. -Garbage pit is over full and it needs to be cleaned up. -There are some smells from garbage pit. -People throw garbage at the backside of Third Row. 

																								
No	Item	Condition	Description and Photos																					
1	(5). Fly proof toilet	Improved <input type="checkbox"/> Same <input checked="" type="checkbox"/> * Worse <input type="checkbox"/> <i>*as last week</i>	<u>Description</u> -All of fly proof toilets are used by people. <table border="1"> <thead> <tr> <th rowspan="2">Condition</th> <th colspan="2">No. of HHs</th> </tr> <tr> <th>This week condition</th> <th>Previous week condition</th> </tr> </thead> <tbody> <tr> <td>Level 1</td> <td>20</td> <td>42</td> </tr> <tr> <td>Level 2</td> <td>10</td> <td>21</td> </tr> <tr> <td>Level 3</td> <td>28</td> <td>0</td> </tr> <tr> <td>Level 4</td> <td>5</td> <td>0</td> </tr> <tr> <td>No Toilet</td> <td>5</td> <td>5</td> </tr> </tbody> </table> <u><Evaluation Criteria></u> Level 1 -No need to repair fly proof toilet -No/rarely toilet unavailable Level 2 -Need to repair fly proof toilet -Rarely toilet unavailable Level 3 -Need to repair fly proof toilet -Often toilet unavailable -As the result of filling the soil and also raining, some toilets are inconvenience to use. Level 4 -Need to repair urgently fly proof toilet -Often toilet unavailable -After filling the soil, some toilets need to be lifted up.	Condition	No. of HHs		This week condition	Previous week condition	Level 1	20	42	Level 2	10	21	Level 3	28	0	Level 4	5	0	No Toilet	5	5	<u>Photos</u>   
Condition	No. of HHs																							
	This week condition	Previous week condition																						
Level 1	20	42																						
Level 2	10	21																						
Level 3	28	0																						
Level 4	5	0																						
No Toilet	5	5																						
	(6). Electricity	Improved <input type="checkbox"/> Same <input checked="" type="checkbox"/> * Worse <input type="checkbox"/>	<u>Description</u> -Electricity comes regularly. -Electric poles and transformer are supported in good foundation.																					

		*as last week	<p><u>Photos</u></p> 
--	--	---------------	---

No	Item	Condition	Description and Photos
2	House Construction	No. of houses not completed (2)	<p><u>Description</u></p> <p>-HH No.1 is almost renovated except fencing the compound, and it will suppose to be finished within next week by the house owner as he would like to do himself.</p> <p>-HH No.5, the construction for kitchen, toilet and water tank seems to be started again.</p> <p>-Soil filling work has almost done for all the compounds of the PAP's, but some houses like HH no. 1 need to be reduced the soil because there have over filled already.</p> <p><u>Photos</u></p> 
3	Living Status of PAPs (Sold house, renting, etc.)	<p><u>Description</u></p> <p>(1) House ownership</p> <p>(1)-1 No. of house that are owned by PAPs (48)</p> <p>(1)-2 No. of house that were sold (20)</p> <p>(2) Living condition</p> <p>(2)-1 No. of houses where PAPs live (38)</p> <p>(2)-2 No. of houses where not original PAPs lives (22)</p> <p>(2)-3 No. of houses where nobody lives (8)</p>	

		Location Map: See ANNEX.2																	
4	Other issues	<p>(1). Drainage condition for rain water in their compounds</p> <p><u>Description</u> -Rainy season is going to start. -Most of the compounds are a bit wet.</p> <table border="1"> <thead> <tr> <th rowspan="2">Condition</th> <th colspan="2">No. of HHs</th> </tr> <tr> <th>This week condition</th> <th>Previous week condition</th> </tr> </thead> <tbody> <tr> <td>Level 1</td> <td>14</td> <td>14</td> </tr> <tr> <td>Level 2</td> <td>30</td> <td>30</td> </tr> <tr> <td>Level 3</td> <td>20</td> <td>20</td> </tr> <tr> <td>Level 4</td> <td>4</td> <td>4</td> </tr> </tbody> </table> <p><Evaluation Criteria> Level 1 -No mud and no standing water with their own drainage system in their compound Level 2 -No mud and no standing water in their compound Level 3 - Some or little mud and standing water in their compound Level 4 -A lot of mud and standing water in their compound</p> <div style="display: flex; flex-wrap: wrap;"> <div style="width: 50%; text-align: center;">  <p>HH No. 47</p> <p>Level 1</p> </div> <div style="width: 50%; text-align: center;">  <p>HH No. 14</p> <p>Level 2</p> </div> <div style="width: 50%; text-align: center;">  <p>HH No. 52</p> <p>Level 2</p> </div> <div style="width: 50%; text-align: center;">  <p>HH No. 11</p> <p>Level 2</p> </div> </div> <p>The soil filling work has just finished and therefore it is still soft and need to wait time for hard.</p>	Condition	No. of HHs		This week condition	Previous week condition	Level 1	14	14	Level 2	30	30	Level 3	20	20	Level 4	4	4
Condition	No. of HHs																		
	This week condition	Previous week condition																	
Level 1	14	14																	
Level 2	30	30																	
Level 3	20	20																	
Level 4	4	4																	
4	(2) Plantation	<p><u>Description</u> -In front of their compounds, they planted shady trees, fruit trees, vegetables and floral plants.</p>																	

Type	No. of HHs	Remarks
Shady tree	12	Albizia, Indian almond, etc. HH No. 2, 3, 14, 19, 20, 21, 25, 27, 29, 32, 41 and 65
Fruit tree	24	Banana, Mango, sugarcane, coconut, citrus, etc. HH No. 2, 3, 4, 7, 8, 9, 11, 17, 21,24, 25, 27, 33, 37, 38, 39, 41, 43, 45, 46, 47, 48, 54 and 65
Vegetable	10	Spices, peas, roselle, etc. HH No. 22, 23, 25, 27, 38, 39, 40, 42,45 and 63
Floral plant	20	Many species. HH No. 2, 9, 14, 15, 17,21, 23, 27, 32, 33, 38, 39, 40, 41, 42, 43, 47, 48, 58 and 65

Photos



4 (3) Livestock

Description


-They are raising chicken, ducks, goats, pigs and cows.
-Even though they have cows, they do not keep their cows in relocation site instead they keep in their farms or other places.

Type	No. of HHs	Remarks
Cow	5	HH No. 3, 18, 42, 47 and 54
Pig	-	-
Goat	1	HH.47
Chicken and ducks	15	HH No. 4, 8, 12, 14, 28, 30, 32, 41, 47, 50, 51, 52, 55, 56 and 62

		<p><u>Photos</u></p> 
5	Remarks	<p>For avoiding from flood, each of the PAPs' compounds have been fenced by retaining wall, the stands of the houses are painted by water proofing paint or making concrete protection. Moreover each of the PAPs' compound had done filling with the soil.</p>

ANNEX.1

As of 1.6.2015



Water is clean and has no sand, no clay and no smell. People use this well for cooking, washing and drinking. A pulley wheel, bucket and a rope have set already but the rope is still small and it needs to be changed with a new big one for convenience using the well.



This hand pump is functioned very well. Water is clean and everyone nearby using this hand pump.



This hand pump is also functioned very well. Water is clean and everyone nearby using this hand pump.



Hand pump isn't functioned.

The well is in good situation. No smell. Water is clean and people living nearby are using this well. A pulley wheel, bucket and a rope have set already but the rope is still small and it needs to be changed with a new big one for convenience using the well.



This hand pump is also functioned very well. Water is clean and everyone living nearby are using this hand pump. Now the raining season is going to be started and the underground water level is raising up and therefore the amount of having clean water is pretty enough to use.



- Closed Well
- New Well (Hand pump)
- Open Well
- Hand Pump
- Private Well

This hand pump is also functioned very well. Water is clean and everyone living nearby are using this hand pump. Now the raining season is going to be started and the underground water level is raising up and therefore the amount of having clean water is pretty enough to use.

