
## **Weekly Field Report**


Surveyor: Zaw La
Date Visited: 18.5.2015
Time Visited: 9:30to 10:30

Weather Condition: Sunny
The last time of heavy raining: -

No	Item	Condition	Description and Photos
1	Condition of -		
	(1). Well	Improved ■* Same □ Worse □ *as last week	Description & Photos: -See ANNEX.1 - Two wells and all hand pumps except near transformer are well functioned, clean water and enough water amount to use as the raining season is nearer and underground water level is raising up. Therefore no problem has heard so far.
	(2). Drainage	Improved □ Same <b>©</b> *	Description -Water level in the drainage canal is near to the bottom.
		Worse □ *as last week	Photos  The stream was repaired and supposed to be smooth water flow in
			this year but need to clear the drainage canal.

(3). Road	Improved □ Same ■* Worse □ *as last week	<u>Description</u> -The roads are a bit wet, but no pr	oblem for traffic so fars.
		Photos Photos	
(4). Garbage	Improved C	Description	
Condition	Improved□ Same <b>©</b> * Worse □	-Garbage pit is used by peopleGarbage pit is over fullThere are some smells from garbPeople throw garbage at the back	
		Garbage Pit	Garbage Pit
		Garbage Pit	Garbage at the backside of Third Row





No	Item	Condition	Description and Photos	
2	House	No. of	<u>Description</u>	
	Construction	houses not	-HH No.1 is almost renovated except fancing and ceiling inside the	
		completed	house, and it will suppose to be finished within next week.	
		(2)	-In HH No.5, the construction for kitchen, toilet and water tank seems	
			stopped.	
			<u>Photos</u>	
			HH No. 1	
3	Living Status	<u>Description</u>		
	of PAPs (Sold	(1) House ownership		
	house,	, , ,	o. of house that are owned by PAPs (48)	
	renting, etc.)		o. of house that were sold (20)	
		(2) Living condition		
		(2)-1 No. of houses where PAPs live (38) (2)-2 No. of houses where not original PAPs lives (22)		
		(2)-3 No. of houses where nobody lives (8)		
		(2) 5 Houses Where Housey Hves (b)		
		Location Map: See ANNEX.2		

### 4 Other issues

(1). Drainage condition for rain water in their compounds

### **Description**

-Rainy season is going to start.

-Most of the compounds are a bit wet.

	No. of HHs	
Condition	This week condition	Previous week condition
Level 1	14	14
Level 2	54	54
Level 3	0	0
Level 4	0	0

### <Evaluation Criteria>

#### Level 1

-No mud and no standing water with their own drainage system in their compound

#### Level 2

-No mud and no standing water in their compound

#### Level 3

- Some or little mud and standing water in their compound

#### Level 4

-A lot of mud and standing water in their compound









## 4 (2) Plantation

## Description

-In front of their compounds, they planted shady trees, fruit trees, vegetables and floral plants.

Туре	No. of HHs	Remarks
Shady tree	12	Albizzia, Indian almond, etc.
		HH No. 2, 3, 14, 19, 20, 21, 25, 27, 29, 32, 41 and
		65

Fruit tree	24	Banana, Mango, sugarcane, coconut, citrus, etc.	
		HH No. 2, 3, 4, 7, 8, 9, 11, 17, 21,24, 25, 27, 33,	
		37, 38, 39, 41, 43, 45, 46, 47, 48, 54 and 65	
Vegetable	10	Spices, peas, roselle, etc.	
		HH No. 22, 23, 25, 27, 38, 39, 40, 42,45 and 63	
Floral plant	20	Many species.	
		HH No. 2, 9, 14, 15, 17,21, 23, 27, 32, 33, 38, 39,	
		40, 41, 42, 43, 47, 48, 58 and 65	

## Photos









# 4 (3) Livestock

# Description

- -They are raising chicken, ducks, goats, pigs and cows.
- -Even though they have cows, they do not keep their cows in relocation site instead they keep in their farms or other places.

Туре	No. of HHs	Remarks
Cow	5	HH No. 3, 18, 42,
		47 and 54
Pig	-	-
Goat	1	HH.47
Chicken and	15	HH No. 4, 8, 12, 14,
ducks		28, 30, 32, 41, 47,
		50, 51, 52, 55, 56
		and 62



ANNEX.1 As of 11.5.2015

Water is clean and has no sand, no clay and no smell. People use this well for cooking and washing. Sometimes they drink. But It need to be set up a set of a pulley wheel, bucket and a rope for convenience using the well.

The well is in good situation. No smell. Water is clean and people living nearby are using this well. But It need to be set up a set of a pulley wheel, bucket and a rope for convenience using the well.



This hand pump is functioned very well.

Water is clean and everyone nearby
using this hand pump.

40

39

63

62 61 60

36

35

37



This hand pump is also functioned very well. Water is clean and everyone nearby using this hand pump.

57 56

33

55 54 53

52

51 50

26



Hand pump isn't functioned.

This hand pump is also functioned very well. Water is clean and everyone living nearby using this hand pump. Now the raining season is going to be started and the underground water level is raising up and therefore the amount of having clean water is pretty enough to use.




\*

45

44

42 41

**Closed Well** 



Open Well





**Private Well** 

This hand pump is also functioned very well. Water is clean and everyone living nearby using this hand pump. Now the raining season is going to be started and the underground water level is raising up and therefore the amount of having clean water is pretty enough to use.

