

Weekly Field Report

No. 4


Surveyor: Sithu Nyein

Date Visited: 09.9.2014







Time Visited: 12:00 to 14:00







Weather Condition: Cloudy & Shower




The last time of heavy raining: 3 days ago





No	Item	Condition	Description and Photos
1	Condition of -		
	(1). Well	Improved <input type="checkbox"/> Same <input checked="" type="checkbox"/> * Worse <input type="checkbox"/> <i>*as last week</i>	Description & Photos: -See ANNEX.1 -Hand Pumps of Well No.6 and No.9 are needed to repair.
	(2). Drainage	Improved <input type="checkbox"/> Same <input checked="" type="checkbox"/> Worse <input type="checkbox"/> <i>*as last week</i>	<u>Description</u> Water level in the drainage canal is near to the bottom. <u>Photos</u> 





No	Item	Condition	Description and Photos
1	(3). Road	Improved <input type="checkbox"/> Same <input checked="" type="checkbox"/> * Worse <input type="checkbox"/> <i>*as last week</i>	<p data-bbox="592 181 735 210"><u>Description</u></p> <p data-bbox="592 215 1362 244">-The roads are almost dry and no problem for traffic as a whole.</p> <hr/> <p data-bbox="592 300 679 329"><u>Photos</u></p> <div data-bbox="614 353 995 636"> </div> <div data-bbox="1031 353 1412 636"> </div> <div data-bbox="614 672 995 954"> </div> <div data-bbox="1031 672 1412 954"> </div>





No	Item	Condition	Description and Photos
1	(4). Garbage Condition	Improved <input type="checkbox"/> Same <input checked="" type="checkbox"/> * Worse <input type="checkbox"/> <i>*as last week</i>	<p><u>Description</u></p> <ul style="list-style-type: none"> -Water level near garbage pit becomes lower. -Garbage pit is used by people. -Smells are emerging from garbage pit. -Especially people who live in third row throw away the garbage in the backside of their compounds over the fence. -Some people put the garbage near electrical transformer. -Garbage is thrown away in the drainage canal. <div style="display: flex; flex-wrap: wrap;"> <div style="width: 50%; text-align: center;"> <p>Garbage Pit</p>  </div> <div style="width: 50%; text-align: center;"> <p>Garbage Pit</p>  </div> <div style="width: 50%; text-align: center;"> <p>Garbage Pit</p>  </div> <div style="width: 50%; text-align: center;"> <p>Garbage at the backside of HH No.49</p>  </div> <div style="width: 50%; text-align: center;"> <p>Near transformer</p>  </div> <div style="width: 50%; text-align: center;"> <p>Drainage canal near HH No.48</p>  </div> </div>

No	Item	Condition	Description and Photos																				
1	(5). Fly proof toilet	Improved <input type="checkbox"/> Same <input checked="" type="checkbox"/> Worse <input type="checkbox"/> <i>*as last week</i>	<p><u>Description</u> -All of fly proof toilets are being used by people.</p> <table border="1"> <thead> <tr> <th rowspan="2">Condition</th> <th colspan="2">No. of HHs</th> </tr> <tr> <th>This week condition</th> <th>Previous week condition</th> </tr> </thead> <tbody> <tr> <td>Level 1</td> <td>42</td> <td>42</td> </tr> <tr> <td>Level 2</td> <td>21</td> <td>21</td> </tr> <tr> <td>Level 3</td> <td>0</td> <td>0</td> </tr> <tr> <td>Level 4</td> <td>0</td> <td>0</td> </tr> <tr> <td>No Toilet</td> <td>5</td> <td>5</td> </tr> </tbody> </table> <p><Evaluation Criteria> Level 1 -No need to repair fly proof toilet -No/rarely toilet unavailable Level 2 -Need to repair fly proof toilet -Rarely toilet unavailable Level 3 -Need to repair fly proof toilet -Often toilet unavailable Level 4 -Need to repair urgently fly proof toilet -Often toilet unavailable</p> <p><u>Photos</u></p>   	Condition	No. of HHs		This week condition	Previous week condition	Level 1	42	42	Level 2	21	21	Level 3	0	0	Level 4	0	0	No Toilet	5	5
Condition	No. of HHs																						
	This week condition	Previous week condition																					
Level 1	42	42																					
Level 2	21	21																					
Level 3	0	0																					
Level 4	0	0																					
No Toilet	5	5																					
(6). Electricity	Improved <input type="checkbox"/> Same <input checked="" type="checkbox"/> * Worse <input type="checkbox"/> <i>*as last week</i>	<p><u>Description</u> -Electricity is coming regularly -Electric poles and transformer are supported in good foundation.</p> <p><u>Photos</u></p>   																					

No	Item	Condition	Description and Photos
2	House Construction	No. of houses not completed (2)	<p><u>Description</u></p> <ul style="list-style-type: none"> -HH No.1 doesn't have ladder and nobody is living -In HH No.5, the construction for kitchen, toilet and water tank seems stopped. Nobody lives. -In HH No.5, sun shade of this house is collapsed due to wind. Wind is not so strong but the quality of the sun shade is not so good enough. <p><u>Photos</u></p> <div style="display: flex; flex-direction: column; align-items: center;">  <div style="display: flex; justify-content: space-around; width: 100%;">   </div> </div>
3	Living Status of PAPs (Sold house, renting, etc.)		<p><u>Description</u></p> <ul style="list-style-type: none"> (1) House ownership <ul style="list-style-type: none"> (1)-1 No. of house that are owned by PAPs (49) (1)-2 No. of house that were sold (19) (2) Living condition <ul style="list-style-type: none"> (2)-1 No. of houses where PAPs live (37) (2)-2 No. of houses where not original PAPs lives (25) (2)-3 No. of houses where nobody lives (6) <p>Location Map: See ANNEX.2</p>

No	Item	Description and Photos																
4	Other issues																	
	(1). Drainage condition for rain water in their compounds	<p><u>Description</u></p> <p>-In this week, there is no heavy rain. -But there are some puddles and muddy areas in most of the compounds.</p> <table border="1"> <thead> <tr> <th rowspan="2">Condition</th> <th colspan="2">No. of HHs</th> </tr> <tr> <th>This week condition</th> <th>Previous week condition</th> </tr> </thead> <tbody> <tr> <td>Level 1</td> <td>10</td> <td>6</td> </tr> <tr> <td>Level 2</td> <td>26</td> <td>24</td> </tr> <tr> <td>Level 3</td> <td>18</td> <td>23</td> </tr> <tr> <td>Level 4</td> <td>14</td> <td>15</td> </tr> </tbody> </table> <p><Evaluation Criteria></p> <p>Level 1 -No mud and no standing water with their own drainage system in their compound</p> <p>Level 2 -No mud and no standing water in their compound</p> <p>Level 3 - Some or little mud and standing water in their compound</p> <p>Level 4 -A lot of mud and standing water in their compound</p> <div style="display: flex; flex-wrap: wrap;"> <div style="width: 50%; text-align: center;">  <p>HH No. 47</p> <p>Level 1</p> </div> <div style="width: 50%; text-align: center;">  <p>HH No. 14</p> <p>Level 2</p> </div> <div style="width: 50%; text-align: center;">  <p>HH No. 52</p> <p>Level 3</p> </div> <div style="width: 50%; text-align: center;">  <p>HH No. 11</p> <p>Level 4</p> </div> </div>	Condition	No. of HHs		This week condition	Previous week condition	Level 1	10	6	Level 2	26	24	Level 3	18	23	Level 4	14
Condition	No. of HHs																	
	This week condition	Previous week condition																
Level 1	10	6																
Level 2	26	24																
Level 3	18	23																
Level 4	14	15																

No	Item	Description and Photos															
4	(2) Plantation	<p><u>Description</u> -In front of their compounds, they planted shady trees, fruit trees, vegetables and floral plants.</p> <table border="1"> <thead> <tr> <th>Type</th> <th>No. of HHs</th> <th>Remarks</th> </tr> </thead> <tbody> <tr> <td>Shady tree</td> <td>12</td> <td>Albizzia, Indian almond, etc. HH No. 2, 3, 14, 19, 20, 21, 25, 27, 29, 32, 41 and 65</td> </tr> <tr> <td>Fruit tree</td> <td>23</td> <td>Banana, Mango, sugarcane, coconut, citrus, etc. HH No. 2, 3, 4, 7, 8, 9, 11, 17, 21, 25, 27, 33, 37, 38, 39, 41, 43, 45, 46, 47, 48, 54 and 65</td> </tr> <tr> <td>Vegetable</td> <td>10</td> <td>Spices, peas, roselle, etc. HH No. 22, 23, 25, 27, 38, 39, 40, 42,45 and 63</td> </tr> <tr> <td>Floral plant</td> <td>19</td> <td>Many species. HH No. 2, 9, 14, 15, 17, 23, 27, 32, 33, 38, 39, 40, 41, 42, 43, 47, 48, 58 and 65</td> </tr> </tbody> </table> <p><u>Photos</u></p> <div style="display: flex; flex-wrap: wrap;"> <div style="width: 50%; text-align: center;">  <p>Near well No.8</p> </div> <div style="width: 50%; text-align: center;">  <p>HH No. 23</p> </div> <div style="width: 50%; text-align: center;">  <p>HH No. 40</p> </div> <div style="width: 50%; text-align: center;">  <p>HH No. 32</p> </div> </div>	Type	No. of HHs	Remarks	Shady tree	12	Albizzia, Indian almond, etc. HH No. 2, 3, 14, 19, 20, 21, 25, 27, 29, 32, 41 and 65	Fruit tree	23	Banana, Mango, sugarcane, coconut, citrus, etc. HH No. 2, 3, 4, 7, 8, 9, 11, 17, 21, 25, 27, 33, 37, 38, 39, 41, 43, 45, 46, 47, 48, 54 and 65	Vegetable	10	Spices, peas, roselle, etc. HH No. 22, 23, 25, 27, 38, 39, 40, 42,45 and 63	Floral plant	19	Many species. HH No. 2, 9, 14, 15, 17, 23, 27, 32, 33, 38, 39, 40, 41, 42, 43, 47, 48, 58 and 65
Type	No. of HHs	Remarks															
Shady tree	12	Albizzia, Indian almond, etc. HH No. 2, 3, 14, 19, 20, 21, 25, 27, 29, 32, 41 and 65															
Fruit tree	23	Banana, Mango, sugarcane, coconut, citrus, etc. HH No. 2, 3, 4, 7, 8, 9, 11, 17, 21, 25, 27, 33, 37, 38, 39, 41, 43, 45, 46, 47, 48, 54 and 65															
Vegetable	10	Spices, peas, roselle, etc. HH No. 22, 23, 25, 27, 38, 39, 40, 42,45 and 63															
Floral plant	19	Many species. HH No. 2, 9, 14, 15, 17, 23, 27, 32, 33, 38, 39, 40, 41, 42, 43, 47, 48, 58 and 65															

No	Item	Description and Photos															
4	(3) Livestock	<p data-bbox="400 297 544 324"><u>Description</u></p> <p data-bbox="400 331 1050 358">-They are raising chicken, ducks, goats, pigs and cows.</p> <p data-bbox="400 365 1406 432">-Even though they have cows, they do not keep their cows in relocation site instead they keep in their farms or other places.</p> <table border="1" data-bbox="400 472 1026 797"> <thead> <tr> <th>Type</th> <th>No. of HHs</th> <th>Remarks</th> </tr> </thead> <tbody> <tr> <td>Cow</td> <td>5</td> <td>HH No. 3, 18, 42, 47 and 54</td> </tr> <tr> <td>Pig</td> <td>1</td> <td>HH No. 2</td> </tr> <tr> <td>Goat</td> <td>2</td> <td>HH No. 50 and 51</td> </tr> <tr> <td>Chicken and ducks</td> <td>15</td> <td>HH No. 4, 8, 12, 14, 28, 30, 32, 41, 47, 50, 51, 52, 55, 56 and 62</td> </tr> </tbody> </table> <p data-bbox="400 804 488 831"><u>Photos</u></p> <div data-bbox="432 846 898 1189">  </div> <div data-bbox="938 846 1401 1189">  </div> <div data-bbox="432 1234 898 1574">  </div> <div data-bbox="938 1234 1401 1574">  </div>	Type	No. of HHs	Remarks	Cow	5	HH No. 3, 18, 42, 47 and 54	Pig	1	HH No. 2	Goat	2	HH No. 50 and 51	Chicken and ducks	15	HH No. 4, 8, 12, 14, 28, 30, 32, 41, 47, 50, 51, 52, 55, 56 and 62
Type	No. of HHs	Remarks															
Cow	5	HH No. 3, 18, 42, 47 and 54															
Pig	1	HH No. 2															
Goat	2	HH No. 50 and 51															
Chicken and ducks	15	HH No. 4, 8, 12, 14, 28, 30, 32, 41, 47, 50, 51, 52, 55, 56 and 62															
5	Remarks																



Water is clean and has no sand, no clay and no smell. People are using this well for cooking and washing. Sometimes they are drinking



Hand pump is functioned. Water is clean and has no sand, no clay but it has smell of mud. People are not using this well



Hand pump isn't functioned. It is need to repair the washer.



Hand pump is functioned. Water is yellow in color and has sand, clay and smell of mud. People are not using this well.

Water is milk in color and has no sand, no clay and no smell. People are using this well for washing.



Hand pump is functioned. Water is clean, and has no sand, no clay and no smell. People are using this well of cooking and washing. Sometimes they are drinking.



-  **Closed Well**
-  **New Well (Hand pump)**
-  **Open Well**
-  **Hand Pump**
-  **Private Well**

Hand pump is functioned. But it is need to repair the handle. Water is clean and has no sand, no clay, and no smell. People are using this well for cooking and washing. Sometimes they are drinking.

