Biweekly Field Report

No.	4		
חוו			
INU.	- 1		

Surveyor Zaw La

Weather Condition


Sunny


Date visited 29 Dec 2017

The last time of heavy raining _____

Time visited 13:30 pm

No	Item	Condition	Description and Photos	
1	(1) Well	Improved□ Same * Worse □ *as last week	 Water from two open-wells is clean and can be used for drinking and living. There are eleven tube wells in the relocation site. Among them, three of the tube wells need to be repaired, but people using water mainly from pipeline water supply system. 	
			Open Well No. 1 Tube Well No. 1 Tube Well No. 2 Tube Well No. 2 Tube Well No. 2	





(4) Garbage Condition	Improved□ Same •* Worse □ *as last week	even in front of their houses bef There are fourteen garbage bins	Site Village Road The right of road, beside the creek and fore they got enough garbage bins. It is are provided and they are kept to the village is almost clean except
		Rubbish bin at the corner of Main Road B and Road No. 1	Rubbish bin at the corner of Main Road B and Road No. 2
		Rubbish bin at the corner of Main Road B and Road No. 3	Rubbish bin at the corner of Main Road B and Road No. 4
		Rubbish bin at Main Road - C	Rubbish bin at the corner of Creek Road and 5 th Street

Rubbish at the creek near 1 st street	Rubbish at the creek near 2 nd street
Rubbish at the creek near Main Road C	Rubbish at the creek near 6 th Street

(5)	Fly
pro	oof
toi	let

Improved□
Same ©*
Worse □
*as last week

- All of the fly proof toilets are used by people.
- No serious problem for toilet for the time being.

	No. of HHs		
Condition	This week condition	Previous	
		week condition	
Level 1	86	86	
Level 2	4	4	
Level 3	0	0	
Level 4	0	0	
No Toilet	0	0	

<Evaluation Criteria>

Level 1

- Fly proof toilet is not needed to be repaired.
- -No/rarely toilet unavailable

Level 2

- Fly proof toilet is needed to be repaired.
- -Rarely toilet unavailable

Level 3

- -- Fly proof toilet is needed to be repaired.
- -Often toilet unavailable
- -As the result of filling the soil and also due to the heavy rain, some toilets are inconvenience to use.

Level 4

- Fly proof toilet is urgently needed to be repaired.
- -Often toilet unavailable

Photos





	(6) Electricity	Improved□ Same • Worse □ *as last week	 Electricity comes regularly. Electric poles and transformer a foundation. 	re being supported with a good
			Transformer No. 1	Transformer No. 2
			Transformer No. 3	Electricity pole at the corner of Main Road B and Road No. 3
No	Item	Condition	Description and Photos	
2	(1)House Construct- ion	No. of houses not completed (4)	-House No.9, there are three houses that planned to build in plot number 9 and 10 as the plots are owned by father and son. The two houses finished const-ruction and left oneHouse No.64, the house construction seems to be stoppedHouse No. 78, the house need to be carried on construction, however PAPs are living nowHouse No. 66, the house construction seems to be stopped.	









3 Other Issues

(1). Drainage condition for rain water in their compounds

Description

	No. of HHs	
Condition	This week	Previous week
	condition	condition
Level 1	63	63
Level 2	5	5
Level 3	0	0
Level 4	0	0

<Evaluation Criteria>

Level 1

-No mud and no standing water with their own drainage system in their compound

Level 2

-No mud and no standing water in their compound

Level 3

- Some or little mud and standing water in their compound

Level 4

-A lot of mud and standing water in their compound

Photos



(2) Plantation

- In front of their compounds, the people planted shady trees, fruit trees, vegetables and floral plants.

Description

-In front of their compounds, the people planted shady trees, fruit trees, vegetables and floral plants.

irces, vegetai	trees, vegetables and floral plants.				
Type	No. of	Remarks			
	HHs				
Shady	15	Albizzia, Indian almond, neem tree, etc.			
tree		HH No. 20, 40, 43, 48, 51, 57, 59, 61, 62, 67,			
		69, 72, 73, 77, 85			
Fruit tree	37	Banana, Mango, sugarcane, coconut, citrus,			
		jack fruit etc.			
		HH No. 3, 15, 17, 20,21, 23, 28, 30, 31, 32,			
		34, 37, 40, 41, 48, 51, 52, 55, 57, 58, 59, 61,			
		62, 63, 67, 68, 70, 71, 72, 73, 77, 78, 82, 85,			
		86, 88			
Vegetable	20	Chili, tomato, bitter gourd, Roselle, gourd,			
		basils, eggplant etc.			
		HH No. 12, 17, 21, 41, 49, 58, 59, 61, 62, 63,			
		67, 68, 70, 71, 72, 73, 77, 82, 85, 86			
Floral	31	Jasmine, poinsettia, orchid, kiss me quick,			
plant		etc.			
		HH No. 3, 5, 6, 8, 10, 12, 13, 14, 17, 20, 21,			
		22, 23, 29, 30, 31, 32, 46, 48, 58, 59, 61, 62,			
		65, 67, 68, 69, 72, 77, 78, 86			

Photos









(3) Livestock

Description

-The people are raising chicken, gooses, ducks and pigs.

Type	No. of HHs	Remarks
Chicken	6	HH No. 13, 14, 21,
		59, 67, 78
Pig	3	HH No. 2, 21, 56
Goose	2	HH No. 40, 67

Photos



